



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|---------------|--|------------|
| RG5-5560-FLM | ACETATO FUSOR HP LJ 2200 | \$ 100.047 |
| RG5-1964-FLM | ACETATO FUSOR HP LJ 5L/6L | \$ 54.634 |
| RB1-8877-000 | ACOPLE HP LJ 4000/4050/4100/5000 | \$ 3.333 |
| 2008593 | ADAPTADOR EPSON TMU 200/300 | \$ 70.806 |
| 0950-3807 | ADAPTADOR HI CAPACITY OFJ G55/G85/G95/R40/R45/V40/PSC700/900 | \$ 118.278 |
| 0950-4199 | ADAPTADOR HP DJ 3300/3400 SERIES | \$ 0 |
| 0957-2094 | ADAPTADOR HP PHOTOSMART 2410/ 2510/ 5510 | \$ 18.000 |
| 11P0100 | ADAPTADOR LEXMARK REF.11P0100 | \$ 13.713 |
| 14C0301 | ADAPTADOR LEXMARK REF.14C0301 | \$ 16.694 |
| 14R0210 | ADAPTADOR LEXMARK REF.14R0210 | \$ 16.675 |
| 17D0057 | ADAPTADOR LEXMARK REF.17D0057 | \$ 16.694 |
| 17E0301 | ADAPTADOR LEXMARK REF.17E0301 | \$ 16.694 |
| 70D0209 | ADAPTADOR LEXMARK REF.70D0209 | \$ 16.694 |
| 12G1826 | ADAPTADOR LEXMARK Z31 | \$ 45.944 |
| 73H09G | ADAPTADOR MOUSE (PS/2 A SERIAL) | \$ 4.308 |
| 73M09G | ADAPTADOR MOUSE (SERIAL A PS/2) | \$ 4.308 |
| 195KPA | ADAPTADOR TECLADO DIN A MINIDIN (AT-PS/2) | \$ 3.686 |
| 195KPB | ADAPTADOR TECLADO MINIDIN A DIN (PS/2-AT) | \$ 3.693 |
| 90263 | AGUJA EPSON DFX 5000+ (.28X124MM) | \$ 2.567 |
| C5884-40005 | ALETA X2 BANDEJA HP DJ 600 SERIES (SALIDA) | \$ 1.106 |
| 99A0026 | ARM ASM TRAY 1 LEXMARK T52X/T62X/OPTRA T | \$ 19.869 |
| RB1-8787-000 | ARM SENSOR ACTUATOR HP LJ 4000/4050/4100 -TRAY 1 | \$ 1.905 |
| RB1-6581-000 | BANDA HP LJ 5SI/8000 | \$ 3.157 |
| P2200-67002 | BANDEJA APOLLO P-2200 | \$ 10.180 |
| RC1-2019-000 | BANDEJA MANUAL HP LJ 1020 (TRAY 1) | \$ 2.000 |
| RB1-8843-000 | BANDEJA POSTERIOR HP LJ 4000/4050 | \$ 29.215 |
| F1798-60918 | BATERIA JORNADA 520/525/540/545 (PALMTOP) | \$ 93.540 |
| PM6-10 | BATERIA PALMA PM6-10 (6V-10AH) | \$ 42.450 |
| 99A1621 | BEARING FUSER LEXMARK OPTRA 4039/4059/69 | \$ 9.501 |
| 99A0143 | BEARING FUSER LEXMARK OPTRAS | \$ 6.840 |
| XG9-0442-000 | BEARING HEAT ROLLER HP LJ 9000 | \$ 10.178 |
| BRG-9000-UP | BEARING HEAT ROLLER HP LJ 9000 | \$ 10.178 |
| XG9-0266-CLN | BEARING HP LJ 8000 | \$ 12.234 |
| XG9-0331-CLN | BEARING HP LJ 8000 | \$ 3.804 |
| XG9-0377-CLN | BEARING HP LJ 8100 | \$ 12.152 |
| XG9-0379-CLN | BEARING HP LJ 8100 | \$ 7.787 |
| BRG- 9000-LOW | BEARING PRESSURE ROLER HP LJ 9000 | \$ 8.739 |
| 2028532 | BIOS EPSON DFX 8500 | \$ 198.288 |
| Y461800705 | BIOS EPSON FX 1050 | \$ 10.467 |
| M20A27JB | BIOS EPSON FX 2170 | \$ 43.276 |
| 2390109 | BIOS EPSON LQ 1070 | \$ 1.231 |
| 2035694 | BIOS EPSON LX 300+ (GRANDE) | \$ 78.263 |
| C6487-60003 | BOARD CARRIAGE HP OFJ 6100/PSC 2100/2110 | \$ 76.977 |
| RG5-4375-000 | BOARD CONTROLLER HP LJ 8100/8150 | \$ 416.989 |
| RG5-4250-000 | BOARD INTERMEDIATE HP LJ 2100 | \$ 51.511 |
| 2081800 | BOARD MAIN EPSON FX 980 | \$ 290.866 |
| 2028925 | BOARD MAIN EPSON FX 980 | \$ 287.282 |
| 2009008 | BOARD MAIN EPSON TM 300A/TM 300B | \$ 397.653 |
| 2022709 | BOARD MAIN EPSON TMU 200 PA | \$ 165.000 |
| C4562-67812 | BOARD MAIN HP DJ 690/692/693/694/695 | \$ 16.756 |
| RM1-0806-000 | BOARD MAIN HP LJ 101X SERIES/1012 | \$ 74.538 |
| Q6508-61005 | BOARD MAIN HP LJ 2410/20/30 | \$ 283.629 |
| C9652-67902 | BOARD MAIN HP LJ 4200 SERIES | \$ 80.000 |
| 1046163 | BOARD PANEL EPSON TMU 675 (134) | \$ 10.000 |
| 2020560 | BOARD PARALLEL EPSON TMU 200PB/PD/220PA/PB/230P/300PD/675P | \$ 90.000 |
| RM1-2314-000 | BOARD PC HP LJ 1020 | \$ 15.000 |
| 9801050LQ | BUJES X2 EPSON LQ 1050 | \$ 5.058 |
| 98TM200 | BUJES X2 EPSON TMU 200 | \$ 7.386 |
| F332001030 | BUS DATOS EPSON FX 286/86E | \$ 1.891 |
| 2089324 | BUS DATOS EPSON LQ 2070 INF.ANC | \$ 16.959 |
| 2089325 | BUS DATOS EPSON LQ 2070 SUP.ANG | \$ 6.532 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|----------------|---|------------|
| 2021269 | BUS DATOS EPSON LQ 2070 SUP.ANG (VER 2089325) | \$ 8.382 |
| 2085778 | BUS DATOS EPSON LQ 2090 | \$ 11.473 |
| 2010975 | BUS DATOS EPSON STY 1000 | \$ 39.987 |
| 1026005 | BUS DATOS EPSON STY 1500 COLOR | \$ 67.379 |
| 1026007 | BUS DATOS EPSON STY 1500 NEGRO | \$ 53.947 |
| 2014128 | BUS DATOS EPSON STY 500 NEGRO | \$ 24.316 |
| 2008871 | BUS DATOS EPSON STY 800 NEGRO | \$ 20.411 |
| 2022450 | BUS DATOS EPSON STY 850 COLOR | \$ 21.507 |
| 2022449 | BUS DATOS EPSON STY 850 NEGRO | \$ 21.507 |
| 2017339 | BUS DATOS EPSON STY II COLOR | \$ 26.751 |
| 2018348 | BUS DATOS EPSON STY PRO | \$ 36.712 |
| 1020613 | BUS DATOS EPSON TM 930 | \$ 1.954 |
| 2012311 | BUS DATOS EPSON TM 950 | \$ 5.810 |
| C1676-60092 | BUS DATOS HP DJ 1200 | \$ 88.438 |
| C2124-80006 | BUS DATOS HP DJ 550 COLOR | \$ 1.231 |
| C2124-80005 | BUS DATOS HP DJ 550 NEGRO | \$ 1.231 |
| C2164-80003 | BUS DATOS HP DJ 600 SERIES COLOR | \$ 1.000 |
| C2145-60032 | BUS DATOS HP DJ 850/870/OFJ 1150 | \$ 0 |
| C4713-60182 | BUS DATOS HP DSJ 230/250/330/350/430/450 | \$ 6.779 |
| C4713-60181 | BUS DATOS HP DSJ 250/230/330/350/450 CORTO | \$ 318.716 |
| C2675-60103 | BUS DATOS HP LJ 1100/1120/1125 | \$ 11.803 |
| 79F4793 | BUS DATOS LEXMARK 2380 | \$ 57.540 |
| 79F4819 | BUS DATOS LEXMARK 2381 | \$ 57.387 |
| PJUP299Z | BUS DATOS PANASONIC KXP 1695 | \$ 46.237 |
| RH2-5440-000 | BUS DATOS SCANNER HP LJ 1200 | \$ 3.604 |
| C5316-80002 | BUS DATOS SCANNER HP OFJ 600/610/700/710 | \$ 32.759 |
| 2033181 | BUS PANEL EPSON LQ 570E | \$ 5.499 |
| 2010513 | BUS PANEL EPSON STY 1000 | \$ 7.030 |
| 2023127 | BUS PANEL EPSON STY 850 | \$ 5.975 |
| 2014158 | BUS PANEL EPSON STY COLOR | \$ 23.340 |
| C5300-60010 | BUS PANEL HP OFJ 1150 | \$ 1.629 |
| RB1-6647-000 | BUSHING CLEATING ROLLER HP LJ 5SI / 8000 | \$ 1.145 |
| RB2-3517-CLN | BUSHING CLEATING ROLLER HP LJ 8100 | \$ 1.960 |
| RB1-6610-CLN | BUSHING HEAT ROLLER HP LJ 8100 | \$ 1.868 |
| BSH-4019 | BUSHING HEAT ROLLER LEXMARK IBM 4019 | \$ 5.700 |
| BSH-4039 | BUSHING HEAT ROLLER LEXMARK IBM 4039 | \$ 5.700 |
| 99A0150 | BUSHING HEAT ROLLER LEXMARK OPTRA S | \$ 1.710 |
| BSH-SM1510-LFT | BUSHING HOT ROLLER LEFT SAMSUNG ML 1510/SCX5112/5312F | \$ 3.073 |
| BSH-SM1510-RGT | BUSHING HOT ROLLER RIGHT SAMSUNG ML 1510/SCX5112/5312 | \$ 3.073 |
| RC1-0988-000 | BUSHING ROD.PRESION HP LJ 2300 USED 2 | \$ 3.073 |
| RS5-1310-CLN | BUSHING ROD.PRESION HP LJ 4000 (IZQ) | \$ 1.762 |
| RS5-1389-000 | BUSHING ROD.PRESION HP LJ 5000/5100 USED 2 | \$ 3.073 |
| BSH-9000-LOW | BUSHING ROD.PRESION HP LJ 9000 | \$ 3.084 |
| RB2-3956-000 | BUSHING ROD.PRESION LEFT HP LJ 1100/3200 | \$ 5.819 |
| 99A0159 | BUSHING ROD.PRESION LEXMARK OPTRA 4039/4059 | \$ 3.610 |
| RB2-3957-000 | BUSHING ROD.PRESION RIGHT HP LJ 1100/3200 | \$ 4.002 |
| JC66-10901A | BUSHING ROLLER PRESSURE FUSING SAMSUNG ML 2250/51/2510/2550 | \$ 5.166 |
| RC1-3665-000 | BUSHING TRANSFER HP LJ 2400/2015/1160 | \$ 4.195 |
| RC1-0922-000 | BUSHING TRANSFER RIGHT HP LJ 2300/2400/P3015 | \$ 4.201 |
| BSH-9000-UP | BUSHING UPPER ROLLER HP LJ 9000 | \$ 3.084 |
| 110306M | CABLE BIDI-SERIAL DE 1.8 MTS (M/M) | \$ 2 |
| 2011447 | CABLE CONECTOR EPSON FX 980 (BOARD MAIN) | \$ 22.371 |
| 2023126 | CABLE CONECTOR EPSON STY 850 | \$ 5.975 |
| RM1-1190-000 | CABLE PANEL HP LJ 4250/4350 | \$ 17.262 |
| 8120-6260 | CABLE PODER HP DJ 3320/6110 | \$ 8.904 |
| 8121-0740 | CABLE PODER HP LJ 1020 | \$ 1.482 |
| 12G1581 | CABLE SENSOR LEXMARK 5016 OPTRA C710/11 | \$ 16.271 |
| USB-AB7.5M | CABLE USB DE 7.5 | \$ 25.000 |
| RB2-1796-CLN | CAM LEFT HP LJ 5000 -TRAY 1 | \$ 9.189 |
| RB2-1797-CLN | CAM RIGHT HP LJ 5000 -TRAY 1 | \$ 9.189 |
| 1046320 | CAP R COVER DETECTOR EPSON TMU 675 (636) | \$ 1.000 |
| CARCA002 | CARCAZA CONECTOR MONITOR 15 PINES | \$ 439 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|--------------|---|------------|
| CARCA001 | CARCAZA CONECTOR MONITOR 9 PINES | \$ 632 |
| QB1-2247-000 | CARRIAGE CANON BJ 210 | \$ 93.875 |
| QG5-0125-000 | CARRIAGE CANON BJC 200 SERIES (CON BUS) | \$ 50.178 |
| 1000928 | CARRIAGE EPSON DFX 8000 | \$ 21.100 |
| 1044188 | CARRIAGE EPSON FX 980 | \$ 4.843 |
| 1020154 | CARRIAGE EPSON TMU 375/370 | \$ 13.581 |
| C6409-40031 | CARRIAGE HP DJ 710/720/810/840 SIN TAPITAS | \$ 30.804 |
| 53590402 | CARRIAGE OKIDATA 320/321 | \$ 16.366 |
| 1236999 | CHASIS EPSON FX 2190 | \$ 6.714 |
| RB2-3516-000 | CLEANING ROLLER HP LJ 5SI/8000/8100 | \$ 5.049 |
| WAN-4019 | CLEANING WAND LEXMARK IBM 4019 | \$ 3.800 |
| WAN-4039 | CLEANING WAND LEXMARK IBM 4039 | \$ 3.990 |
| RB1-2190-000 | CLIP PICKUP HP LJ 4000 | \$ 444 |
| 1328134 | CLIP THERMOFUSE LEXMARK IBM 4049 | \$ 1.520 |
| 99A0145 | CLIP THERMOFUSE LEXMARK IBM 4059 | \$ 1.520 |
| 12G0065 | CLUTCH ASSY PICK ROLLER LEXMARK OPTRA E310 | \$ 10.241 |
| C6426-40103 | CLUTCH HP DJ 930/950/970/OFJ G55/G85/G95 PIÑON | \$ 1.403 |
| RH7-5192-000 | CLUTCH HP LJ 5000 | \$ 71.910 |
| C3964A | COATING KIT HP LJ 5/5M | \$ 160.129 |
| C3106A | COATING KIT HP LJ COLOR | \$ 177.680 |
| 1046279 | COIL, LEVER DRIVE A EPSON TMU 675 (621) | \$ 5.271 |
| 1046280 | COIL, LEVER DRIVE B EPSON TMU 675 (622) | \$ 5.659 |
| C0002 | COMBO TECLADO-MOUSE GENIUS INHALAMBRICO | \$ 62.068 |
| RM1-0542-000 | CONTACT ASSY, TONER HP LJ 1300 SERIES | \$ 17.851 |
| 1008613 | CORREA EPSON STY MFP CX 4900 | \$ 25.000 |
| 1009135 | CORREA EPSON TM 300/370/375 | \$ 5.282 |
| 1078957 | CORREA EPSON TM 930 CORTA | \$ 8.536 |
| C4530-40238 | CORREA HP DJ 2200/2250/2000 | \$ 6.036 |
| C3320-00002 | CORREA HP DJ 3320/3420 CON SEGURO | \$ 5.000 |
| C2145-40058 | CORREA HP DJ 820/850/870/890 | \$ 11.168 |
| C4723-60235 | CORREA HP DSJ 3000/3500/3800 | \$ 151.427 |
| BLT-4000-DPX | CORREA HP LJ 4000 | \$ 7.008 |
| 12G6150 | CORREA LEXMARK X73 -SCANNER | \$ 2.206 |
| 53349701 | CORREA OKIDATA 321T | \$ 2 |
| 1293964 | COVER ACOUSTIC EPSON STY PHOTO R320 | \$ 24.846 |
| 200464200 | COVER ASSY XEROX PASHER 8200 (LOGO) | \$ 37.475 |
| 1090496 | COVER ASSY, FRONT EPSON FX 1180+ | \$ 52.776 |
| RC1-2112-000 | COVER ASSY, LEFT HP LJ 1020 | \$ 2.000 |
| RC1-4148-000 | COVER ASSY, LEFT HP LJ 2400 | \$ 42.473 |
| RC1-0287-000 | COVER ASSY, LEFT HP LJ 4200 | \$ 10.000 |
| RG0-1014-000 | COVER ASSY, PAPER TRAY HP LJ 1200/1000/1300 | \$ 22.052 |
| RB2-2857-000 | COVER ASSY, REAR HP LJ 2100 SERIES | \$ 38.491 |
| RG5-5545-000 | COVER ASSY, RIGHT DIMM HP LJ 2200 | \$ 77.442 |
| RC1-5635-000 | COVER ASSY, RIGHT HP LJ 1020 | \$ 2.000 |
| RM1-0046-000 | COVER ASSY, RIGHT HP LJ 4200 | \$ 15.000 |
| 1408792L | COVER CABLE OPENING TRAY 2 LEXMARK 4049 | \$ 37.230 |
| 1381549 | COVER D-ROLLER LEXMARK IBM 4039 | \$ 13.301 |
| 1381842 | COVER D-ROLLER LEXMARK IBM 4039 | \$ 13.301 |
| 1039105 | COVER D-ROLLER LEXMARK OPTRA IBM 4019 | \$ 9.501 |
| 1039540 | COVER D-ROLLER LEXMARK OPTRA IBM 4019/4029/4039 | \$ 5.700 |
| RC1-0288-000 | COVER FORMATTER HP LJ 4200 | \$ 5.000 |
| RB2-3524-000 | COVER FUSER HP LJ 8100 | \$ 31.645 |
| RB2-5961-000 | COVER FUSER HP LJ 9000 | \$ 13.879 |
| RB1-3481-000 | COVER GEAR CLUSTER ASSY HP LJ 4/4+/5 | \$ 15.000 |
| RC1-0019-000 | COVER INNER FRONT RIGHT HP LJ 4200/4300 | \$ 10.000 |
| 99A2010 | COVER KIT UPPER FRONT LEXMARK T522 | \$ 46.427 |
| 99A1510 | COVER LEFT DOOR LEXMARK T612/T614/T620 | \$ 63.169 |
| RC1-0291-000 | COVER LOWER REAR DUPLEXER HP LJ 4200/4300 | \$ 5.000 |
| 1064676 | CUTTER EPSON TM 300 | \$ 9.389 |
| 1079045 | CUTTER EPSON TM 950/930 | \$ 11.381 |
| RG5-5645-000 | DELIVERY ASSY HP LJ 9000 WITH FANS 3,4,6 | \$ 147.418 |
| RG5-5643-000 | DELIVERY ASSY HP LJ 9000/9000MFP | \$ 361.659 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|--------------|---|------------|
| 1046548 | DETECTOR ASSY FRONT COVER EPSON TMU 675 (691) | \$ 6.000 |
| 1046549 | DETECTOR ASSY REAR COVER EPSON TMU 675 (692) | \$ 6.000 |
| 1046578 | DETECTOR H.P. ASSY EPSON TMU 675 (707) | \$ 5.000 |
| 1046547 | DETECTOR PAPER EJECT EPSON TMU 675 (690) | \$ 17.220 |
| 1046557 | DETECTOR VALIDATION ASSY EPSON TMU 675 (697) | \$ 9.209 |
| C3967A | DRUM HP LJ 5/5M | \$ 500.000 |
| 56106601 | DRUM OKIDATA OL 400/800/810/20/830/840/850 | \$ 123.104 |
| JC96-02682A | ELA RETARD SAMSUNG ML 2550/2551 | \$ 55.240 |
| C2670-60118 | ENCODER HP DJ 1000/1100/1120/1125 | \$ 8.493 |
| C2693-67031 | ENCODER HP DJ 1180/1200/1220/1280/9300 (DISK) | \$ 8.119 |
| C2684-60208 | ENCODER HP DJ 2500+/2000/CLR PRO CAD C7777A | \$ 40.331 |
| C2145-80016 | ENCODER HP DJ 820/850/855/870/890/OFJ 1150/1170/1175 | \$ 6.048 |
| EXTRA001 | EXTRACTOR BUJES FX 1170/1180/1050/LQ 1070 | \$ 60.000 |
| 12G0128 | FAN COOLING LEXMARK OPTRA E310/312 | \$ 56.866 |
| P2200-67004 | FIJADOR BANDEJA APOLLO P-2200 | \$ 3.240 |
| 12G0051 | FLAG PAPER EXIT SENSOR LEXMARK E310 | \$ 2.265 |
| 1381669 | FLAG PAPER OUT LEXMARK IBM 4039/4049 | \$ 7.411 |
| FLG-4019/39 | FLAG SENSOR LEXMARK IBM 4019/4029/4039 | \$ 7.411 |
| FKG15A006 | FLYBACK REF.FKG15A006 SAMSUNG 450B/550 | \$ 26.188 |
| HR46089 | FLYBACK REF.HR 46089 SAMSUNG SYNCMASTER 3NE | \$ 32.300 |
| 12G6122 | FRAME MIDDLE ASM LEXMARK X83/X85 | \$ 62.391 |
| F353253020 | FRAME TR, LEFT EPSON LX 810 | \$ 6.928 |
| 1259757 | FRAME TR, RIGHT EPSON FX 1180+/880+ | \$ 702 |
| 12G1931 | FRICITION PAD LEFT LEXMARK OPTRA E310/312 | \$ 4.877 |
| 12G1932 | FRICITION PAD RIGHT LEXMARK OPTRA E310/312 | \$ 4.877 |
| FUSI30A | FUSIBLE 30 AMPERIOS | \$ 172 |
| 2028489 | FUSING ASSY EPSON EPL 5700 | \$ 515.055 |
| RG5-0454-000 | FUSING ASSY HP LJ 4/4M | \$ 278.502 |
| RG5-0676-390 | FUSING ASSY HP LJ 4P/4L/4ML/4MP | \$ 256.164 |
| RM1-2522-000 | FUSING ASSY HP LJ 5200 | \$ 559.374 |
| RG5-0046-530 | FUSING ASSY HP LJ IIIISI/4SI | \$ 271.618 |
| 69G8312 | FUSING ASSY LEXMARK E/E+/EP | \$ 461.734 |
| 11A7390 | FUSING ASSY LEXMARK ES/E | \$ 267.237 |
| 1381640 | FUSING ASSY LEXMARK R/LX/LNX | \$ 298.758 |
| 99A1187 | FUSING ASSY LEXMARK S1620/1625/1650/1655/1855 | \$ 205.000 |
| 56P0648 | FUSING ASSY LEXMARK T420 | \$ 176.571 |
| 12G4184 | FUSING ASSY LEXMARK W820 | \$ 700.000 |
| JC96-02693C | FUSING ASSY SAMSUNG ML 2151/2550/2551 | \$ 172.414 |
| JC96-03808A | FUSING ASSY SAMSUNG ML 4200/4100 | \$ 163.321 |
| 126K12920 | FUSING ASSY XEROX DOCUPRINT P 8E | \$ 74.863 |
| RG5-4134-000 | FUSING ELEMENT HP LJ 2100/2200 | \$ 199.333 |
| 1046307 | GEAR CARRIAGE DRIVE TRANSMISSION EPSON TMU 675 (634) | \$ 6.000 |
| RG5-0876-000 | GEAR CLUSTER ASSY HP LJ 4+/5/4 | \$ 33.558 |
| RL1-0013-000 | GEAR MOUNT PICKUP ROLLER SHAFT HP LJ 4200/4250/4300/4350 | \$ 6.871 |
| 56P0634 | GEAR PAPER FEED LEXMARK T420 | \$ 4.754 |
| 1009107 | GEAR RIBBON DRIVE EPSON TM 375/300 | \$ 1.911 |
| 1046415 | GEAR RIBBON INTERMEDIATE EPSON TMU 675 (683) | \$ 6.000 |
| 1046413 | GEAR RIBBON REDUCTION EPSON TMU 675 (682) | \$ 6.000 |
| 1235949 | GEAR RIBBON TAKE-UP EPSON TM 220 | \$ 3.200 |
| 1046587 | GEAR RIBBON TAKE-UP EPSON TMU 675 (712) | \$ 9.343 |
| 1235980 | GEAR TAKE-UP DRIVE PULLEY EPSON TM 200/220/270 | \$ 3.246 |
| Y544102001 | GEAR TAKE-UP EPSON TMU 200/300/375/TM 270 | \$ 8.903 |
| 1074735 | GEAR TAKE-UP EPSON TMU 270/375 SERIES | \$ 3.477 |
| 12G0102 | GEAR, DRIVE FEED LEXMARK OPTRA E310/E312//E312L | \$ 27.288 |
| RS6-0445-000 | GEAR, DRIVE ROLLER REGISTRATION HP LJ 2100/2200/2300/2430 | \$ 2.240 |
| B702700001 | GRASA EPSON G-37 CAFE | \$ 13.910 |
| 1061834 | GROUNDING PLATE HEAD EPSON LX 300+ | \$ 849 |
| 1052121 | GROUNDING PLATE HEAD EPSON LX 300+ | \$ 1.596 |
| 90137 | GUIA CABEZA EPSON LQ 1070 | \$ 16.495 |
| 90138 | GUIA CABEZA EPSON LQ 2170 | \$ 16.503 |
| 351110600 | GUIDE ASM UPPER XEROX PASHER 8200 | \$ 27.864 |
| RC1-1964-000 | GUIDE CARTRIDGE LEFT HP LJ 1020 | \$ 1.000 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|---------------|---|------------|
| RC1-1963-000 | GUIDE CARTRIDGE RIGHT HP LJ 1020 | \$ 1.000 |
| RG5-3548-000 | GUIDE PAPER ASSY HP LJ 5000/5100 SERIES | \$ 56.207 |
| 1046394 | GUIDE PAPER, SLIP EPSON TMU 675 | \$ 2.771 |
| RG5-4582-000 | GUIDE PLATE ASSY HP LJ 1100/3200 | \$ 6.227 |
| RG5-1577-000 | GUIDE PLATE HP LJ 4V/4MV | \$ 36.520 |
| C2985A | HARD DRIVE 3.2 GB EIO HP LJ 4100 SERIES | \$ 379.083 |
| RC1-4058-000 | HINGE RIGHT HP LJ 2400 | \$ 4.225 |
| JC72-00536A | HOLDER PAD LARGE SAMSUNG ML-1210/ 1250/ 1430/ 4500/ SF-531P | \$ 2.893 |
| JC72-00125B | HOLDER PAD RIGHT SAMSUNG | \$ 1.183 |
| JC61-00580A | HOLDER SEPARATION PAD SAMSUNG SCX 4200/1710 | \$ 4.832 |
| 1017361 | HOLDER SLIP PAPER INSERTION DECTECT EPSON TMU 675 (606) | \$ 6.000 |
| JC61-01173A | HOUSING M PICK UP B ML 1610/SCX 4521/CLP300 | \$ 1.593 |
| 74LS365A | INTEGRADO MONITOR REF.74LS365A COMPUERTA PUERTO | \$ 15.697 |
| LM1283N | INTEGRADO MONITOR REF.LM1283N CODIFICADOR COLOR | \$ 8.764 |
| LM324N | INTEGRADO MONITOR REF.LM324N | \$ 1.961 |
| 2013945 | INTEGRADO REF. 141AF EPSON FX 1180 (IC3) | \$ 179.456 |
| X440072920 | INTEGRADO REF. 2903D EPSON DFX 8500 (IC203) | \$ 7.324 |
| X440072940 | INTEGRADO REF. 2904D EPSON DFX 8500 (IC102) | \$ 5.641 |
| 2011730 | INTEGRADO REF. 591D EPSON DFX 8500/5000+ (IC13) | \$ 12.920 |
| 2012489 | INTEGRADO REF. 7166F EPSON DFX 8500/FX 1180 (IC12) | \$ 11.536 |
| X422350069 | INTEGRADO REF. 74LS06 EPSON FX 1180 (IC9) | \$ 11.400 |
| X422350079 | INTEGRADO REF. 74LS07 EPSON DFX 8500/FX 1170 (IC6) | \$ 10.747 |
| X422350089 | INTEGRADO REF. 74LS08 EPSON DFX 8500 (IC16) | \$ 7.141 |
| 2005177 | INTEGRADO REF. 74LS241 EPSON DFX 5000+ (IC14) | \$ 20.472 |
| X422352459 | INTEGRADO REF. 74LS245 EPSON DFX 5000+ (IC5) | \$ 21.791 |
| X422350749 | INTEGRADO REF. 74LS74A EPSON DFX 8500 (IC17) | \$ 8.108 |
| 2025169 | INTEGRADO REF. A2917SEB EPSON FX 1180 (IC11) | \$ 29.862 |
| 2024473 | INTEGRADO REF. ATMEL008 EPSON DFX 8500 (IC11) | \$ 18.128 |
| 2011704 | INTEGRADO REF. E05A87AA EPSON DFX 5000+ (IC7) | \$ 120.858 |
| 2027659 | INTEGRADO REF. E05B36BE EPSON DFX 8500 (IC1) | \$ 106.758 |
| 2025363 | INTEGRADO REF. E05B50YA EPSON FX 1180 (IC2) | \$ 58.701 |
| X462701438 | INTEGRADO REF. HC14 EPSON DFX 8500 (IC1) | \$ 11.719 |
| 2020806 | INTEGRADO REF. HM514170AJ7 EPSON DFX 8500 IC14 | \$ 194.838 |
| 2017554 | INTEGRADO REF. IC18 EPSON DFX 8500 | \$ 11.353 |
| 2023322 | INTEGRADO REF. IMP95C061BF EPSON DFX 8500 (IC2) | \$ 153.819 |
| X420300070 | INTEGRADO REF. LS07 EPSON FX 1170 (SOCKET) | \$ 6.918 |
| 2012966 | INTEGRADO REF. MAX232CWE EPSON DFX 8500 (IC9) | \$ 39.956 |
| X422651889 | INTEGRADO REF. SN75188 EPSON DFX 5000+ (IC17) | \$ 22.104 |
| 2002357 | INTEGRADO REF. SN75189 EPSON DX 5000+ (IC13) | \$ 15.931 |
| STA485A | INTEGRADO REF. STA485A EPSON DFX 9000 | \$ 50.000 |
| X440660130 | INTEGRADO REF. STK66013Z EPSON DFX 8000 | \$ 239.098 |
| 2024331 | INTEGRADO REF. STK720B EPSON DFX 8500 (C204) | \$ 52.184 |
| F1798-60932 | INVERTER JORNADA 520/525/540/545 (PALMTOP) | \$ 195.828 |
| J2590-69001 | JET DIRECT HP LJ 4/4+/5 | \$ 68.821 |
| J3113-69001 | JET DIRECT HP LJ 5000/8000/2100/4050/CLR 4550 | \$ 100.000 |
| 394277-161 | KEYBOARD ASSY PS/2 COMPAQ PRESARIO M2310LA/V2400 | \$ 133.694 |
| 1044163 | KIT PIÑONES EPSON FX 980 | \$ 54.457 |
| F344208000 | KIT PIÑONES EPSON LQ 2550 | \$ 1.000 |
| 1039271 | KIT TORNILLOS LEXMARK IBM 4019/5E/6/6A/10A | \$ 2.657 |
| 99A0075 | KIT TORNILLOS LEXMARK OPTRA C1250/1650/2420/T610/T612 | \$ 6.259 |
| 12G0445 | KIT TORNILLOS LEXMARK OPTRA M410/412 | \$ 16.662 |
| FCL4000 | LABEL CAUTION FUSER HP | \$ 1.127 |
| RS5-8380-CLN | LABEL CAUTION FUSER HP LJ 4/4+/5/5SI/8100 | \$ 1.401 |
| RS5-8591-000 | LABEL CAUTION FUSER HP LJ 5SI / 800 | \$ 1.047 |
| RS6-8030-CLN | LABEL CAUTION FUSER HP LJ 8100/8500 | \$ 1.868 |
| RH7-4070-000 | LAMPARA #1 HP LJ 5SI | \$ 14.182 |
| RH7-4126-000 | LAMPARA #1 HP LJ 8100 (90V-600W) | \$ 18.738 |
| LMP-9000-110A | LAMPARA #1 HP LJ 9000 | \$ 13.365 |
| RH7-4071-000 | LAMPARA #2 HP LJ 5SI | \$ 17.070 |
| RH7-4127-000 | LAMPARA #2 HP LJ 8100 (90V-450W) | \$ 18.738 |
| LMP-9000-110B | LAMPARA #2 HP LJ 9000 | \$ 13.365 |
| LMP-9000-110C | LAMPARA #3 HP LJ 9000 | \$ 13.365 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|--------------|--|------------|
| RH7-4046-000 | LAMPARA HP LJ 4 | \$ 19.834 |
| RH7-4054-000 | LAMPARA HP LJ 4+/5 | \$ 9.443 |
| RH7-4044-000 | LAMPARA HP LJ 4V (110V) | \$ 18.382 |
| RF1-3303-000 | LAMPARA HP LJ IIP/IIIP | \$ 13.876 |
| 1383311 | LAMPARA LEXMARK IBM 4019 | \$ 19.952 |
| 1381011 | LAMPARA LEXMARK IBM 4039/4049 | \$ 19.952 |
| 99A0141 | LAMPARA LEXMARK OPTRA 1250/1255/1650 (110V-500W) | \$ 19.952 |
| 99A0140 | LAMPARA LEXMARK OPTRA 2450/2420 (110V-750W) | \$ 19.952 |
| 99A1639 | LAMPARA LEXMARK OPTRA T (110V-550W) VER.11K0550 | \$ 18.074 |
| 99A1547 | LAMPARA LEXMARK OPTRA T (115V-875W) | \$ 32.304 |
| 99A2050 | LAMPARA LEXMARK OPTRA T522 (115V-630W) | \$ 6.639 |
| 4713-001135 | LAMPARA SAMSUNG | \$ 62.362 |
| 4713-001181 | LAMPARA SAMSUNG 110V | \$ 71.030 |
| 4713-001183 | LAMPARA SAMSUNG ML 1510/1710/1520P/225 | \$ 53.195 |
| 4713-001203 | LAMPARA SAMSUNG ML 1610/1615/1620 ML 2010/2015/2510/2570 | \$ 71.609 |
| 4713-001155 | LAMPARA SAMSUNG ML 2015 | \$ 65.356 |
| 4713-001136 | LAMPARA SAMSUNG ML-1210/1250/1440/1450 | \$ 56.236 |
| LMP-P8E-110 | LAMPARA XEROX P8E (110) | \$ 20.009 |
| 1058355 | LATERAL IZQUIERDO EPSON LX 300+ | \$ 6.012 |
| RB2-6351-CLN | LEVER DELIVERY HP LJ 2200 | \$ 5.606 |
| RA0-1100-CLN | LEVER HOLDING, LEFT FUSER HP LJ 1200 | \$ 3.912 |
| LVR-4200-LFT | LEVER HOLDING, LEFT HP LJ 4200/4300 | \$ 4.748 |
| RA0-1101-CLN | LEVER HOLDING, RIGHT FUSER HP LJ 1200 | \$ 3.955 |
| JC66-00815A | LEVER M KICKER SAMSUNG CPL 300/SEX 4521 | \$ 13.520 |
| 1046574 | LEVER MOTOR T.P DETECT ASSY EPSON TMU 675 | \$ 7.333 |
| RF5-2694-000 | LEVER SENSOR DELIVERY HP LJ 5SI/8000 | \$ 1.502 |
| RB1-6614-CLN | LEVER SENSOR DELIVERY HP LJ 5SI/8000 | \$ 2.491 |
| RC1-0209-000 | LEVER SENSOR FLAG HP LJ 4200 | \$ 5.000 |
| RB2-1807-CLN | LEVER SENSOR FLAG HP LJ 5000/5100 | \$ 3.893 |
| RB2-2836-000 | LEVER SENSOR HP LJ 2200 | \$ 2.647 |
| RB1-8880-CLN | LEVER SENSOR HP LJ 4000 | \$ 1.448 |
| RB2-1782-CLN | LEVER SENSOR PAPER HP LJ 5000/5100 -TRAY 2 | \$ 2.336 |
| 99A0135 | MAIN DRIVE ASSY DEVELOPER LEXMARK OPTRA S4059 | \$ 62.022 |
| RM1-1066-000 | MAIN DRIVE ASSY HP LJ 4250/4350/4200/4300 | \$ 85.292 |
| 12G0321 | MAIN DRIVE ASSY LEXMARK 4045 OPTRA M410/412 | \$ 220.392 |
| RM1-0001-000 | MAIN DRIVE GEAR ASSY HP LJ 4200/4300 SERIES | \$ 15.000 |
| RG5-5656-000 | MAIN DRIVE GEAR ASSY HP LJ 9000/9040/9050 | \$ 319.236 |
| Q2651-67911 | MEMORIA DIMM HP LJ 2300 | \$ 123.797 |
| MM256 | MEMORIA DIMM 256 MB PC133 | \$ 42.143 |
| C3195-60151 | MEMORIA HP DSJ 750/755 (A.02.10) | \$ 112.540 |
| C2029-60001 | MEMORIA HP LJ 4 | \$ 1.231 |
| MM32S | MEMORIA SIMM 32 MB | \$ 55.646 |
| MM4USB | MEMORIA USB 4GB | \$ 38.267 |
| MIC01A | MICROFONO GENIUS | \$ 6.155 |
| 2011558 | MOTOR CARRIAGE EPSON DFX 5000+ | \$ 123.104 |
| 2002936 | MOTOR CARRIAGE EPSON LQ 1070/1070+/570 | \$ 13.843 |
| 2030904 | MOTOR CARRIAGE EPSON TMU 675 (733)/TMH 6000 | \$ 15.000 |
| 2056372 | MOTOR CARRIAGE EPSON TMU 675/TMH 6000 | \$ 33.828 |
| C4557-60003 | MOTOR CARRIAGE HP DJ 710/720/810/840 | \$ 22.157 |
| C6090-60328 | MOTOR CARRIAGE HP DSJ 5000 | \$ 239.509 |
| RK2-0523-000 | MOTOR DC HP LJ 2400 SERIES | \$ 68.400 |
| 1046516 | MOTOR LEVER DRIVE ASSY EPSON TMU 675 (686) | \$ 15.000 |
| RK2-0799-000 | MOTOR MAIN HP LJ 1020 | \$ 5.000 |
| RG5-0765-000 | MOTOR MAIN HP LJ 4L/4P | \$ 69.498 |
| RH7-1343-000 | MOTOR MAIN STEPPER HP CLR LJ 4500/4550 | \$ 59.602 |
| Q1261-60018 | MOTOR MAIN STEPPER HP DSJ 815 MFP | \$ 402.864 |
| 2019040 | MOTOR PAPER FEED EPSON FX 2170/2180 | \$ 69.587 |
| 2030928 | MOTOR PAPER FEED EPSON TMU 675 (739) | \$ 15.000 |
| 2025899 | MOTOR PLATEN GAP EPSON DFX 8500 | \$ 36.781 |
| 1046555 | MOUNTING PLATE, LEVER COIL SUB ASSY EPSON TMU 675 | \$ 4.577 |
| 1046355 | MOUNTING PLATE,J/S SOLENOID EPSON TMU 675 (774) | \$ 3.178 |
| 3500110-001 | MOUSE GENIUS PS/2 | \$ 8.592 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|---------------|---|---------------|
| 4025 | MOUSE USB OPTICO | \$ 18.966 |
| 1067828 | NO FACTURAR - ROLLER INTERMEDIATE HOLDER EPSON TMU 270/375 | \$ 15.229 |
| C2688-67037 | OIL PAD ABSORBER HP DJ 2200/2250 EST.SERVICIO | \$ 2.001 |
| C2642-60206-G | OIL PAD ABSORBER HP DJ 400 SERIES | \$ 30 |
| C5870-80007 | OIL PAD ABSORBER HP DJ 710/720/810/840 EST.SERVICIO | \$ 1.345 |
| JC75-00050B | PAD SIDE LEFT SAMSUNG 1210/1250 | \$ 2.776 |
| JC75-00051B | PAD SIDE RIGHT SAMSUNG ML 1210/1250 | \$ 2.776 |
| 1232267 | PALANCA ACER. CABEZA EPSON FX 2190 | \$ 2.075 |
| 1050405 | PALANCA ACER. CABEZA EPSON LX 300+ | \$ 612 |
| 1026484 | PALANCA EPSON | \$ 2.696 |
| C2124-40110 | PALANCA ESTACION SERV. HP DJ 560/540 (CORTA) | \$ 2.129 |
| C2124-40111 | PALANCA ESTACION SERV. HP DJ 560/540 (LARGA) | \$ 9.777 |
| C2164-00016 | PALANCA ESTACION SERV. HP DJ 600/660/680 | \$ 11.806 |
| 1039410 | PALANCA PAPEL EPSON FX 2180 VER. 1235583 | \$ 5.674 |
| 1251311-1 | PALANCA PAPEL EPSON FX 2190/FX 890 | \$ 2.000 |
| 1004917 | PALANCA PAPEL EPSON LQ 1070/1070+/570 | \$ 6.290 |
| 1025323 | PALANCA SENSOR POSTERIOR EPSON FX 1180 | \$ 885 |
| 1025324 | PALANCA SENSOR POSTERIOR EPSON FX 1180/880 | \$ 3.146 |
| PJDT80Z | PALANCA TRACTOR PANASONIC KXP 1624 | \$ 3.800 |
| 1235585-1 | PALANCA TRANSMISSION EPSON FX 2190 | \$ 1.001 |
| 1235585 | PALANCA TRANSMISSION EPSON FX 890/2190/LQ 2080 | \$ 819 |
| 1262597-1 | PANEL CONTROL EPSON FX 2190/FX 890 | \$ 5.000 |
| 1050321 | PANEL CONTROL EPSON LQ 570E (SIN SHEET) | \$ 28.451 |
| C6417-60004 | PANEL CONTROL HP DJ 695/640 | \$ 16.496 |
| RG1-4276-000 | PANEL CONTROL HP LJ 4200/4300 SERIES | \$ 30.000 |
| C2642-60262 | PAPER ADJUSTMENT HP DJ 400 | \$ 21.196 |
| RC1-0072-000 | PAPER DELIVERY LOWER ASSY HP LJ 4200 (FUSING) | \$ 5.942 |
| 1046581 | PAPER END DETECTOR ASSY EPSON TMU 675 (710) | \$ 15.221 |
| 12G4541 | PAPER FEED CLUTCH ASSEMBLY LEXMARK E32X | \$ 40.231 |
| RG5-2643-000 | PAPER FEED GUIDE HP LJ 4000/4050 | \$ 67.840 |
| C4209-PFKIT | PAPER FEED KIT, LJ 2200 | \$ 10.000 |
| 12G0446 | PAPER OUTPUT LEXMARK OPTRA M410/412 | \$ 5.678 |
| RM1-2091-000 | PAPER PICKUP ASSY HP LJ 1020 | \$ 15.000 |
| RM1-0034-000 | PAPER PICKUP DRIVE ASSY HP LJ 4200/4300 SERIES (PLATINA) | \$ 15.000 |
| JC75-00072A | PAPER PICKUP DRIVE ASSY SAMSUNG ML-1210/ 1430/4500/ SF-531P | \$ 3.975 |
| GL-1.0 | PEGANTE RESISTENCIA 1.0 OZ (28G) | \$ 7.303 |
| 99A1056 | PICK ARM ASM LEXMARK OPTRA S1250/1650/2450/1620/610/612 | \$ 112.695 |
| 56P1325 | PICK ARM ASSY LEXMARK T630 (TRAY 500 SHEET) | \$ 132.809 |
| C2670-60138 | PICKUP ROLLER ASSY HP DJ 1100/1120 | \$ 39.664 |
| C2684-60302 | PICKUP ROLLER ASSY HP DJ 2500/2500+/CLR PRO CAD C7777A | \$ 46.746 |
| RG1-1792-000 | PICKUP ROLLER ASSY HP LJ IIP/IIIP (TRAY 1) | \$ 53.982 |
| 12G0067 | PICKUP ROLLER ASSY LEXMARK OPTRA E310/312 | \$ 50.232 |
| RB2-0744-000 | PICKUP ROLLER HP CLR LJ 4500/4550 (TRAY 1) | \$ 1.527 |
| RF5-2092-000 | PICKUP ROLLER HP CLR LJ 4500/4550 (TRAY 2 AUTOM) | \$ 3.298 |
| RB1-2632-000 | PICKUP ROLLER HP LJ 4/4M (TRAY ADIC) | \$ 3.123 |
| RB1-2650-000 | PICKUP ROLLER HP LJ 4+/4 (TRAY ADIC) | \$ 3.606 |
| RB1-3029-000 | PICKUP ROLLER HP LJ 4L | \$ 2.740 |
| RB1-3368-000 | PICKUP ROLLER HP LJ 4P (IN PICKUP ASSY) | \$ 7.249 |
| RB1-1386-000 | PICKUP ROLLER HP LJ 4V | \$ 2.900 |
| RB1-7983-000 | PICKUP ROLLER HP LJ 5/4+ (TRAY ADIC) | \$ 2.342 |
| RF5-2636-000 | PICKUP ROLLER HP LJ 5000/5100 | \$ 19.100 |
| RB1-6332-000 | PICKUP ROLLER HP LJ 5P/6P (TRAY 2) | \$ 4.547 |
| RF5-2708-000 | PICKUP ROLLER HP LJ 8000/8100 | \$ 2.654 |
| RA1-3851-000 | PICKUP ROLLER HP LJ II/III | \$ 4.695 |
| RF5-0081-000 | PICKUP ROLLER HP LJ IIISI/4SI | \$ 5.512 |
| RA1-7573-000 | PICKUP ROLLER HP LJ IIP/IIIP | \$ 3.888 |
| RA1-7674-000 | PICKUP ROLLER HP LJ IIP/IIIP | \$ 3.888 |
| 12G0323 | PICKUP ROLLER LEXMARK 4045 OPTRA M410/412 | \$ 14.589 |
| 12G1378 | PICKUP ROLLER LEXMARK 5016 OPTRA C710/712 | \$ 10.773 |
| 69G5480 | PICKUP ROLLER LEXMARK IBM 4039/49 | \$ 19.583 |
| 99A0071 | PICKUP ROLLER LEXMARK OPTRA S1250/1650/2420/T610/T612 | \$ 67.573 |
| JC96-02683A | PICKUP ROLLER SAMSUNG ML 2550/2551 | \$ 91.793 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|----------------|---|------------|
| C4704-40059 | PINCH ARM LEVER, HP DSJ 2000CP/ 3000CP SERIES | \$ 25.049 |
| PJUG200Z | PIÑON #2 CINTA PANASONIC KXP 3696 | \$ 6.395 |
| 1328243 | PIÑON #2 LEXMARK 4039/OPTRA L/R/LX/RX | \$ 4.657 |
| PJDG50142Z | PIÑON #9 CINTA PANASONIC KXP 3696 | \$ 6.657 |
| 1004906 | PIÑON CORREA EPSON LQ 1070 (PULLEY) | \$ 878 |
| F353003110 | PIÑON ENGRANE #2 EPSON LX 810 | \$ 4.031 |
| C8136A-GEAR-G | PIÑON ENGRANE HP DJ 9300 | \$ 20.000 |
| F346003500 | PIÑON EPSON DFX 5000/8000/8500 (RIBBON FEED TRANSMISSION) | \$ 1.280 |
| 1074257 | PIÑON EPSON DFX 5000/8000/8500 (RIBBON FEED TRANSMISSION) | \$ 1.470 |
| 1067837 | PIÑON EPSON TM 270/375 (INTERMEDIATE) | \$ 1.969 |
| 1020144 | PIÑON EPSON TM 375/300 (RIBBON TAKE-UP SHAFT ASSY) | \$ 13.505 |
| 1067251 | PIÑON EPSON TMU 200 (J FEED ROLLER SHAFT HOLDER) | \$ 1.360 |
| RU5-0389-000 | PIÑON GRANDE (201T) RIGHT SIDE PRINTER HP LJ 2400 | \$ 33.381 |
| RS5-0185-000 | PIÑON HP LJ 4V (13T) | \$ 1.857 |
| RS5-0182-000 | PIÑON HP LJ 4V (14T) | \$ 1.857 |
| RS5-0183-000 | PIÑON HP LJ 4V (14T) | \$ 1.857 |
| RS5-0194-000 | PIÑON HP LJ 4V (14T) | \$ 1.857 |
| RS5-0184-000 | PIÑON HP LJ 4V (18T) (TAPA U. FUSORA) | \$ 1.857 |
| F353001070 | PIÑON KIT EPSON LX 810 (DRIVING) | \$ 4.366 |
| 40355101 | PIÑON LINE FEED OKIDATA 320T/321T/390T/391T/184T | \$ 7.908 |
| PJDGA0135Z | PIÑON PANASONIC KXP 3196 | \$ 2.577 |
| 1004934 | PIÑON RODILLO EPSON LQ 1070 | \$ 1.115 |
| F353252020 | PIÑON RODILLO EPSON LX 810 | \$ 645 |
| 1044973 | PIÑON TRACTOR EPSON FX 1170/1050 | \$ 489 |
| RB1-6130-000 | PIÑON TRAY 1 HP LJ 5000/5100 | \$ 7.787 |
| RS6-0442-000 | PIÑON U. FUSORA HP LJ 2100 (14T) | \$ 4.995 |
| RS6-0458-000 | PIÑON U. FUSORA HP LJ 2100 (26T) | \$ 7.140 |
| RU5-0378-000-G | PIÑON U. FUSORA HP LJ 2400 SERIES (20T) | \$ 76.131 |
| RS5-0388-000 | PIÑON U. FUSORA HP LJ 4+/5 (42T) | \$ 2.197 |
| RS5-0921-000 | PIÑON U. FUSORA HP LJ 4000 | \$ 6.668 |
| RS5-0922-000 | PIÑON U. FUSORA HP LJ 4000 | \$ 6.668 |
| RS5-0316-000 | PIÑON U. FUSORA HP LJ 4L | \$ 1.851 |
| RS5-0603-000 | PIÑON U. FUSORA HP LJ 4V (39T) | \$ 2.940 |
| RS5-0637-000 | PIÑON U. FUSORA HP LJ 5P/6P (24T-BEIGE) | \$ 4.375 |
| RS5-0752-000 | PIÑON U. FUSORA HP LJ 5SI/8100 (14T) | \$ 1.547 |
| RS5-0751-000 | PIÑON U. FUSORA HP LJ 5SI/8100 (18T) | \$ 2.940 |
| RS6-0506-000 | PIÑON U. FUSORA HP LJ 8100 (23T) | \$ 4.642 |
| RS6-0505-000 | PIÑON U. FUSORA HP LJ 8100 (26T) | \$ 5.945 |
| GR-8100-3T | PIÑON U. FUSORA HP LJ 8100 (3T) | \$ 3.178 |
| RS6-0507-000 | PIÑON U. FUSORA HP LJ 8100 (54T) | \$ 8.821 |
| RS5-0020-000 | PIÑON U. FUSORA HP LJ II | \$ 3.888 |
| GR-4019-38T | PIÑON U. FUSORA LEXMARK IBM 4019 | \$ 7.411 |
| GR-4019-18T | PIÑON U. FUSORA LEXMARK IBM 4019 (18T) | \$ 4.750 |
| 1328124 | PIÑON U. FUSORA LEXMARK IBM 4039/4049 (38T) | \$ 7.411 |
| 99A0148 | PIÑON U. FUSORA LEXMARK OPTRA S (26T) | \$ 4.560 |
| 99A0157 | PIÑON U. FUSORA LEXMARK OPTRA S (50T) | \$ 4.750 |
| B100166012 | PLAIN WASHER EPSON DFX 5000 (8X0.5X15) | \$ 1.007 |
| C2684-60304 | PLATE ASSY HP DJ 2500C+/2500C | \$ 81.560 |
| RC1-5637-000 | PLATE ASSY HP LJ 1020 | \$ 5.000 |
| RG0-1001-000 | PLATE ASSY RIGHT HP LJ 1200/1000/33X0 SERIES | \$ 71.895 |
| 1328467 | PLENUM SPRING LEXMARK 4039 LASER PRINTER | \$ 8.192 |
| 277919-001 | POWER SUPPLY 220W 12V | \$ 180.476 |
| P4680-63021 | POWER SUPPLY BRIO BA300/700/VECTRA XE310 | \$ 181.115 |
| 2080687 | POWER SUPPLY EPSON FX 890/LQ 590 | \$ 68.688 |
| 2033288 | POWER SUPPLY EPSON LQ 570E | \$ 106.992 |
| RG5-4021-000 | POWER SUPPLY HP CLR LJ 8500/8000/8150 | \$ 440.708 |
| C6426-60081 | POWER SUPPLY HP DJ 3820 | \$ 35.000 |
| RM1-2315-000 | POWER SUPPLY HP LJ 1020 | \$ 15.000 |
| 12G6793 | POWER SUPPLY LEXMARK 4010 OPTRA E210 | \$ 227.094 |
| D8520-63001 | POWER SUPPLY NETSERVER LC 2000 | \$ 981.508 |
| F413100000 | PRINT HEAD EPSON FX 286E | \$ 33.505 |
| F418000000 | PRINT HEAD EPSON LQ 2550 | \$ 129.318 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|---------------|--|------------|
| F047001 | PRINT HEAD EPSON STY 200/CLR IIS NEGRO | \$ 82.623 |
| F061001 | PRINT HEAD EPSON STY 300 | \$ 86.242 |
| F058000 | PRINT HEAD EPSON STY 400/440/740 | \$ 199.901 |
| F049001 | PRINT HEAD EPSON STY 500/CLR II COLOR | \$ 66.632 |
| F055100 | PRINT HEAD EPSON STY 5000/7000/7500/9500 | \$ 201.645 |
| F075000 | PRINT HEAD EPSON STY PHOTO 1270/2000 | \$ 248.967 |
| C4800A | PRINT HEAD HP DJ 2000/2500 #10 NEGRO | \$ 1.007 |
| 1381635 | PRINT HEAD LEXMARK 4049 OPTRA L/R/LX/LNX/RX/RT | \$ 770.314 |
| 79F4792 | PRINT HEAD LEXMARK IBM 2300+/2380/2390/2381 | \$ 210.661 |
| 55017301 | PRINT HEAD OKIDATA 193 | \$ 5.815 |
| 55023501 | PRINT HEAD OKIDATA 294 | \$ 6.924 |
| 50114601 | PRINT HEAD OKIDATA 320T/321T | \$ 60.046 |
| 725-3651 | PRINT HEAD OKIDATA 5578/PM060 | \$ 135.415 |
| 54135907 | PRINT HEAD OKIDATA 82A/83A | \$ 6.155 |
| 54135910 | PRINT HEAD OKIDATA 84A/92/93 | \$ 6.155 |
| PJWHP1180M | PRINT HEAD PANASONIC KXP 1180 | \$ 213.076 |
| 1046305 | PULLEY CARRIAGE TRANSMISSION EPSON TMU 675 (632) | \$ 6.000 |
| UNDCD-RW | QUEMADOR CD-RW | \$ 50.039 |
| 5W6.20HJ | RESISTENCIA FUENTE EPSON DFX 8000 | \$ 381 |
| RG9-1494-HEAT | RESISTENCIA HP LJ 1200 (220V) | \$ 35.564 |
| RG5-4132-HEAT | RESISTENCIA HP LJ 2100 | \$ 37.693 |
| RM1-0354-HEAT | RESISTENCIA HP LJ 2300 | \$ 36.208 |
| RM1-1820-HEAT | RESISTENCIA HP LJ 2600 | \$ 20.000 |
| RG5-2659-HEAT | RESISTENCIA HP LJ 4000 | \$ 43.822 |
| RM1-0013-HEAT | RESISTENCIA HP LJ 4200 | \$ 46.230 |
| RM1-0101-HEAT | RESISTENCIA HP LJ 4300 110V | \$ 39.343 |
| C4530-40288 | RETAINER CR HP DJ 2000/CXI/2200/2250 | \$ 1.731 |
| RB2-3947-000 | RETAINER SEPARATION PAD HP LJ 1100/3200 | \$ 1.717 |
| 1020146 | RIBBON DRIVE PLATE ASSY EPSON TMU 375/370 | \$ 6.613 |
| 1046577 | RIBBON DRIVE PLATE ASSY EPSON TMU 675 (706) | \$ 5.978 |
| PJZU2P1123U | RIBBON MASK PANASONIC KXP 1180 | \$ 8.137 |
| PJUG85Z | RIBBON MASK PANASONIC KXP 1624/2664 | \$ 14.765 |
| PJZU1P1695M | RIBBON MASK PANASONIC KXP 1695 | \$ 14.290 |
| PJZUP2124M | RIBBON MASK PANASONIC KXP 2124 | \$ 55.369 |
| SL-21/40H | RMF - CARTRIDGE SEAL HP LJ 2100/2200/4000/4100 | \$ 1.631 |
| SL-50H | RMF - CARTRIDGE SEAL HP LJ 5000 | \$ 1.451 |
| SLF-21/40H | RMF - CARTRIDGE SEAL WITH FOAM HP LJ 2100/2200/4000/4100 | \$ 2.046 |
| SLF-50H | RMF - CARTRIDGE SEAL WITH FOAM HP LJ 5000 | \$ 2.242 |
| CP-5000 | RMF - CONTACT WASHER FOR CARTRIDGE HP LJ 5000 | \$ 659 |
| DB-50H | RMF - DOCTOR BLADE HP LJ 5000 | \$ 11.214 |
| DB-12H | RMF - DOCTOR BLADE HP LJ 1200 | \$ 6.594 |
| DB-21H | RMF - DOCTOR BLADE HP LJ 2100/2200 | \$ 6.597 |
| DB-40H | RMF - DOCTOR BLADE HP LJ 4000 | \$ 6.737 |
| DB-41H | RMF - DOCTOR BLADE HP LJ 4100 | \$ 6.597 |
| DB-AX | RMF - DOCTOR BLADE HP LJ 5L/6L | \$ 5.937 |
| DB-81H | RMF - DOCTOR BLADE HP LJ 8100 | \$ 8.378 |
| MRSB-12H | RMF - MAG ROLLER SEALING BLADE HP LJ 1200 | \$ 633 |
| MRSB-EX/21/40 | RMF - MAG ROLLER SEALING BLADE HP LJ 2100/2200/4000/4/4+/5 | \$ 640 |
| MRS-12H | RMF - MAG ROLLER SLEEVE HP LJ 1200 | \$ 13.853 |
| MRS-40H | RMF - MAG ROLLER SLEEVE HP LJ 2100/2200/4000/4/4+/5 | \$ 16.022 |
| MRS-50H | RMF - MAG ROLLER SLEEVE HP LJ 5000 | \$ 18.471 |
| MRS-AX | RMF - MAG ROLLER SLEEVE HP LJ 5L/6L/1100 | \$ 13.194 |
| MRS-81H | RMF - MAG ROLLER SLEEVE HP LJ 8100 | \$ 18.471 |
| OPC-81H | RMF - ODISSEY OPC DRU WITH GEAR HP LJ 8100 | \$ 46.179 |
| OPC-12H | RMF - ODISSEY OPC DRUM WITH GEAR HP LJ 1200 | \$ 25.068 |
| OPC-21H | RMF - ODISSEY OPC DRUM WITH GEAR HP LJ 2100/2200 | \$ 35.623 |
| OPC-40H | RMF - ODISSEY OPC DRUM WITH GEAR HP LJ 4000 | \$ 28.969 |
| OPC-41H | RMF - ODISSEY OPC DRUM WITH GEAR HP LJ 4100 | \$ 36.943 |
| OPC-50H | RMF - ODISSEY OPC DRUM WITH GEAR HP LJ 5000 | \$ 38.526 |
| OPC-AX | RMF - ODISSEY OPC DRUM WITH GEAR HP LJ 5L/6L/1100 | \$ 19.659 |
| RB-21/40H | RMF - RECOVERY BLADE HP LJ 2100/2200/4000/4100 | \$ 474 |
| RB-50H | RMF - RECOVERY BLADE HP LJ 5000 | \$ 659 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|--------------|---|-----------|
| TNR-12H-150 | RMF - TONER HP LJ 1200 150G | \$ 8.971 |
| TNR-40H-380 | RMF - TONER HP LJ 4000 380G | \$ 16.874 |
| TNR-41H-400 | RMF - TONER HP LJ 4100 400G | \$ 17.152 |
| TNR-50H-420 | RMF - TONER HP LJ 5000 420G | \$ 19.791 |
| TNR-AX-140 | RMF - TONER HP LJ 5L/6L 140G | \$ 8.180 |
| WB-21H | RMF - WIPER BALDE HP LJ 2100/2200 | \$ 8.576 |
| WB-12H | RMF - WIPER BLADE HP LJ 1200 | \$ 8.576 |
| WB-40H | RMF - WIPER BLADE HP LJ 4000 | \$ 6.737 |
| WB-41H | RMF - WIPER BLADE HP LJ 4100 | \$ 6.597 |
| WB-50H | RMF - WIPER BLADE HP LJ 5000 | \$ 9.235 |
| WB-AX | RMF - WIPER BLADE HP LJ 5L/6L | \$ 8.576 |
| WB-81H | RMF - WIPER BLADE HP LJ 8100 | \$ 9.169 |
| C3764-60551 | RODAMIENTO HP LJ 5SI | \$ 29.769 |
| RB1-9181-000 | RODILLO EXIT ASSY HP LJ 5P/6P/4P (3 ROLLER UF) | \$ 7.154 |
| 12G4496 | ROLL IDLER LEXMARK OPTRA E320 | \$ 22.222 |
| 12G4492 | ROLLER ASM IDLE LEXMARK E320 | \$ 5.307 |
| JC72-20902A | ROLLER ASM SAMSUNG ML 2510/2550/2551/25702571/3051/3561 | \$ 3.544 |
| RB2-3546-CLN | ROLLER CLEANING HP LJ 5SI/8000/8100 | \$ 5.606 |
| 12G0084 | ROLLER DELIVERY ASSY LEXMARK 5016 OPTRA C710/712 | \$ 6.268 |
| RF5-2603-CLN | ROLLER DELIVERY HP LJ 2100 | \$ 13.301 |
| RM1-0371-CLN | ROLLER DELIVERY HP LJ 2300 | \$ 4.417 |
| RB1-8798-CLN | ROLLER DELIVERY HP LJ 4000 | \$ 14.017 |
| RB1-6606-CLN | ROLLER DELIVERY HP LJ 5SI/8000 | \$ 14.017 |
| RF5-1521-000 | ROLLER EXIT ASSY HP LJ 5L/6L | \$ 14.375 |
| 12G4493 | ROLLER EXIT REDRIVE LEXMARK E320 | \$ 17.516 |
| RF5-2830-000 | ROLLER FACE-DOWN HP LJ 1100 | \$ 7.454 |
| RB2-1998-000 | ROLLER FACE-DOWN, UPPER HP LJ 5000/5100 (USED 4) | \$ 2.732 |
| RF0-1003-000 | ROLLER FACE-UP HP LJ 1200 | \$ 11.350 |
| RB2-2898-CLN | ROLLER FEED HP LJ 2100 | \$ 12.303 |
| RB2-3490-000 | ROLLER FEED HP LJ 2100/2200 (TRAY 3) | \$ 10.023 |
| JC66-00598A | ROLLER FEED SAMSUNG ML1210/50/1430/1450/2250/2251 | \$ 21.053 |
| JC66-00526A | ROLLER FEED SAMSUNG ML-1510/1710/2250/2251/3051 | \$ 21.849 |
| JC75-00054A | ROLLER FEED SAMSUNG ML-1710 | \$ 22.601 |
| RB2-5948-000 | ROLLER FUSING HP LJ 9000 | \$ 92.530 |
| 1383322 | ROLLER FUSING LEXMARK IBM 4019/4029/40 | \$ 27.934 |
| 1381146 | ROLLER FUSING LEXMARK IBM 4039/4049 | \$ 32.304 |
| 99A0149 | ROLLER FUSING LEXMARK OPTRA 2450/2420 | \$ 43.706 |
| 69G9977 | ROLLER FUSING LEXMARK OPTRA 4026 | \$ 47.506 |
| 99A1521 | ROLLER FUSING LEXMARK OPTRA 4069 010/212/717 | \$ 51.307 |
| 99A1549 | ROLLER FUSING LEXMARK OPTRA 4069 414/616 | \$ 51.307 |
| 12G0079 | ROLLER FUSING LEXMARK OPTRA E4044 | \$ 51.307 |
| 99A0562 | ROLLER FUSING LEXMARK OPTRA S1250/2450 | \$ 43.706 |
| 55044901 | ROLLER FUSING OKIDATA 8W | \$ 52.340 |
| JC71-00012B | ROLLER FUSING SAMSUNG ML1210/ML1250 | \$ 19.459 |
| UFR-P8E | ROLLER FUSING XEROX P8E UPPER | \$ 22.677 |
| JC66-00601A | ROLLER HEAT SAMSUNG ML 1710/1510/RX3120 | \$ 67.022 |
| JC66-00597A | ROLLER HEAT SAMSUNG ML 2550/2551 | \$ 77.404 |
| RB2-3931-000 | ROLLER IDLER HP LJ 1100/3200 | \$ 2.000 |
| 1067831 | ROLLER INTERMEDIATE DRIVE EPSON TMU 270/375 (BLANCO) | \$ 11.493 |
| RM1-0012-000 | ROLLER PAPER FEED HP LJ 4200 | \$ 83.888 |
| RB1-6598-000 | ROLLER PAPER FEED HP LJ 5SI/8000 | \$ 8.202 |
| RB1-6561-000 | ROLLER PAPER FEED HP LJ 5SI/8000 | \$ 7.738 |
| 12G4490 | ROLLER PAPER FEED LEXMARK E322 | \$ 14.408 |
| RC1-0070-000 | ROLLER PRESSURE HP LJ 4200/4300 | \$ 72.044 |
| RB1-3100-000 | ROLLER PRESSURE HP LJ 4L/4P | \$ 23.637 |
| RB1-1443-000 | ROLLER PRESSURE HP LJ 4V | \$ 63.451 |
| RB1-5472-000 | ROLLER PRESSURE HP LJ 4V/4MV | \$ 67.695 |
| LPR-5200 | ROLLER PRESSURE HP LJ 5200 | \$ 41.124 |
| RB1-9210-000 | ROLLER PRESSURE HP LJ 6P | \$ 61.910 |
| RB2-5921-000 | ROLLER PRESSURE HP LJ 9000 | \$ 92.530 |
| 12G0086 | ROLLER PRESSURE LEXMARK 4044 OPTRA E310/E312 | \$ 91.532 |
| 1368637 | ROLLER PRESSURE LEXMARK IBM 4019/4029 | \$ 53.017 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|--------------|--|------------|
| 1329928 | ROLLER PRESSURE LEXMARK IBM 4039/4049 | \$ 53.017 |
| 99A0160 | ROLLER PRESSURE LEXMARK OPTRA 1250/1650 | \$ 53.017 |
| 69G9978 | ROLLER PRESSURE LEXMARK OPTRA 4026 | \$ 57.958 |
| 12G1388 | ROLLER PRESSURE LEXMARK OPTRA C710 | \$ 201.678 |
| 99A2038 | ROLLER PRESSURE LEXMARK T522 | \$ 24.143 |
| JC75-00091A | ROLLER PRESSURE SAMSUNG ML 1210/1250 | \$ 84.502 |
| JC66-00600A | ROLLER PRESSURE SAMSUNG ML 1510/1710/1750/2510/2570 | \$ 88.220 |
| JC66-00599A | ROLLER PRESSURE SAMSUNG ML 2550 | \$ 104.903 |
| LPR-P8E | ROLLER PRESSURE XEROX P8E | \$ 36.017 |
| RM1-0011-000 | ROLLER REGISTRATION HP LJ 4200 | \$ 15.000 |
| RG5-4303-000 | ROLLER REGISTRATION HP LJ 8100/8150 | \$ 312.469 |
| RB2-3057-000 | ROLLER TENSION HP LJ 2100 SERIES | \$ 1.520 |
| RG5-5662-000 | ROLLER TRANSFER ASSY HP LJ 9000/9040/9050 | \$ 32.660 |
| RM1-0740-000 | ROLLER TRANSFER HP CLR LJ 3500/3550/3700 SERIES | \$ 217.178 |
| RM1-1471-000 | ROLLER TRANSFER HP LJ 3390/1160/1320 | \$ 18.412 |
| RF5-0349-000 | ROLLER TRANSFER HP LJ 4/4+/5 | \$ 13.042 |
| RF5-2112-000 | ROLLER TRANSFER HP LJ 4500 | \$ 44.818 |
| RG5-0141-000 | ROLLER TRANSFER HP LJ IIIISI/4SI | \$ 21.597 |
| 1381008 | ROLLER TRANSFER LEXMARK IBM 4039/4049 | \$ 128.778 |
| JC97-01576A | ROLLER TRANSFER SAMSUNG ML 1210/ 1250/ 3110/ 3210 | \$ 53.998 |
| JC66-00725A | ROLLER TRANSFER SAMSUNG ML 1520P/SCX-4100/4521 | \$ 57.220 |
| JC97-01793A | ROLLER TRANSFER SAMSUNG ML 1710/1750 | \$ 54.323 |
| 1046386 | ROLLER,PAPER FEED EPSON TMU 675 (666) | \$ 12.813 |
| RB1-8794-RG | RUBBER GEAR, PRESSURE ROLLER HP LJ 4000 | \$ 1.557 |
| RB1-3109-000 | RUBBER GEAR, PRESSURE ROLLER HP LJ 4L/5L/5P | \$ 3.781 |
| JC96-02733A | RX DRIVE SAMSUNG ML 1710/1750 | \$ 107.825 |
| RG5-5421-000 | SCANNER HP LJ 3200 | \$ 254.037 |
| RG5-3497-000 | SCANNER HP LJ 6L | \$ 259.113 |
| 101N01343 | SCANNER XEROX PE16 | \$ 115.023 |
| 12G3841 | SEGURO CARRO LEXMARK FORMS PRINTER 9/24 | \$ 37.227 |
| 1073532 | SEGURO RODILLO EPSON FX 1170/LQ 870/LQ 1170 | \$ 705 |
| F333003100 | SEGURO RODILLO EPSON LX 810 | \$ 1.595 |
| 119579501 | SENSOR ASSY DRUM XEROX PASHER 8200 | \$ 42.000 |
| C2642-60289 | SENSOR PAPEL HP DJ 420 (PALANCA) | \$ 5.704 |
| C5870-40024 | SENSOR PAPEL HP DJ 710/720/810/840 | \$ 1.023 |
| WG8-5364-000 | SENSOR PAPEL HP LJ 2200 (PHOTO SENSOR) | \$ 1.644 |
| F346151000 | SENSOR PLATEN GAP EPSON DFX 5000/5000+/8000 | \$ 45.268 |
| RB1-7181-000 | SEPARATION ARM HP LJ 5L/6L | \$ 2.016 |
| 56P0691 | SEPARATION ARM LEXMARK OPTRA E322 | \$ 10.188 |
| 12G6779 | SEPARATION ARM PAD LEXMARK E210 | \$ 2.000 |
| RB1-6613-000 | SEPARATION CLAW HP LJ 5SI | \$ 2.222 |
| RB2-3531-CLN | SEPARATION CLAW HP LJ 8100 | \$ 2.336 |
| 1427473 | SEPARATION CLAW LEXMARK IBM 4039/49 | \$ 2.850 |
| 99A0833 | SEPARATION CLAW LEXMARK OPTRA 4059/4069 | \$ 2.850 |
| JC97-02217A | SEPARATION PAD HOLDER SAMSUNG ML 1610/4521/SCX 4521 | \$ 5.553 |
| RB2-6254-000 | SEPARATION PAD HP LJ 2200 (TRAY 1) HOLDER | \$ 5.631 |
| RF5-2399-CLN | SEPARATION PAD HP LJ 5000 (USED 2) | \$ 5.274 |
| 12G1168 | SEPARATION PAD LEXMARK OPTRA C710 (PLATE TRAY) | \$ 612 |
| JC61-01169A | SEPARATION PAD SAMSUNG 1610/CLP-300/DELL 1100 | \$ 4.794 |
| C2642-60284 | SERVICE STATION HP DJ 400/420 | \$ 4.246 |
| 1046303 | SHAFT CARRIAGE GUIDE EPSON TMU 675 (631) | \$ 5.000 |
| 12G1260 | SHAFT LEXMARK 5016 | \$ 1.007 |
| 1005157 | SHAFT RELEASE EPSON FX 880+/890/LQ590 | \$ 6.983 |
| 1041618 | SHAFT TAKE-UP GEAR EPSON TMU 200 SERIES | \$ 3.247 |
| 1051403 | SHAFT TR DRIVE EPSON LX 300.(EJE TRACTOR) | \$ 9.717 |
| 1044043 | SHEET PANEL EPSON FX 980 | \$ 3.837 |
| 1051396 | SHEET PANEL EPSON LQ 570E | \$ 4.166 |
| 1046573 | SLIP T.O.F DETECT ASSY EPSON TMU 675 (703) | \$ 4.000 |
| 99A0815 | SMART CARTRIDGE CONTACT LEXMARK OPTRA T610/612/614/616 | \$ 16.247 |
| RG5-1875-000 | SOLENOIDE FACE-UP HP LJ 8100/ 8150 | \$ 49.759 |
| RH7-5315-000 | SOLENOIDE HP LJ 1000/1005/1150/1300/33X0 | \$ 2.655 |
| RH7-5253-000 | SOLENOIDE HP LJ 2100 | \$ 16.551 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|---------------|---|------------|
| RH7-5357-000 | SOLENOIDE HP LJ 4200 TRAY 1 | \$ 5.000 |
| 12G0047 | SOLENOIDE PICKUP ROLLER CLUTCH LEXMARK OPTRA E310 | \$ 18.410 |
| 99A1511-SOP-G | SOPORTE COVER ASM LOWER FRONT LEXMARK T62X/T52X (X 2) | \$ 15.000 |
| 12G1268 | SOPORTE DERECHO LEXMARK 5016 OPTRA C710/07 | \$ 3.559 |
| 12G0075 | SOPORTE LEXMARK 210/OPTRA E310/E312/E312L | \$ 12.838 |
| 1328222 | SOPORTE LEXMARK 403910/404912/ OPTRA | \$ 37.172 |
| 1046362 | SPRING ASSIST PAPER GUIDE EPSON TMU 675 (653) | \$ 859 |
| C4530-00105 | SPRING BELT HP LJ 2000/2200/2250/2500 | \$ 384 |
| RB1-3108-000 | SPRING DELIVERY HP LJ 4P/4L/5P/6P | \$ 1.177 |
| 1005186 | SPRING EXTENSION EPSON FX 1170 | \$ 1.003 |
| 1046274 | SPRING FORM STOPPER EPSON TMU 675 (620) | \$ 917 |
| RS5-2502-000 | SPRING HP LJ 1100/3100/3200 | \$ 621 |
| 1025356 | SPRING LEAF CR EPSON LQ 2070 | \$ 1.757 |
| 99A1927 | SPRING LEXMARK OPTRA T/T52X | \$ 22.509 |
| 12G0121 | SPRING PAD ASM LOWER OPTRA E310/E312 | \$ 2.060 |
| 12G0068 | SPRING PAD ASM REAR OPTRA E310/E312 SERIES | \$ 2.060 |
| 1025325 | SPRING SENSOR POSTERIOR EPSON FX 1180 | \$ 612 |
| 1027682 | SPRING TAKE-UP TORQUE EPSON TMU 200/375 SERIES | \$ 1.407 |
| RS6-2030-000 | SPRING TENSION HP LJ 2100/2200/CLR LJ 2500 | \$ 1.445 |
| RA0-1026-000 | SPRING TORSION HP LJ 1150/1300 SERIES | \$ 1.252 |
| JC72-01001A | STACKER SEPARATION SAMSUNG ML 2510/2570/2571/3051 | \$ 2.390 |
| 13212 | SWITCH ENCENDIDO EPSON DFX 5000/5000+/8000/8500 | \$ 1.334 |
| 2030853 | SWITCH PANEL CIRCUIT BOARD ASSY EPSON TMU 675 (204) | \$ 10.000 |
| 1041935 | TAKE-UP ROLLER ASSY EPSON TMU /200PA/ 675 (126) | \$ 11.586 |
| 1009560 | TAPA ACRILICA EPSON FX 1170 | \$ 54.158 |
| 1066760 | TAPA ACRILICA EPSON FX 880 | \$ 65.491 |
| C6659-60050 | TAPA CARRO HP DJ 700/710/720/725 (CARTUCHO NEGRO) | \$ 63.170 |
| C4713-40038 | TAPA CARRO HP DSJ 250C (D-SIZE) | \$ 3.906 |
| 1266429 | TAPA FRONTAL EPSON FX 2190 | \$ 21.986 |
| 1036539 | TAPA FRONTAL EPSON FX 880 | \$ 10.000 |
| RC1-5630-000 | TAPA FRONTAL HP LJ 1020 (LOGO) | \$ 3.000 |
| RB2-3526-CLN | TAPA LATERAL IZQUIERDA HP LJ 8100 | \$ 7.008 |
| C5300-40012 | TAPA SUPERIOR HP OFJ 1150C | \$ 14.945 |
| 99A1142 | TAPA U.FUSORA LEXMARK OPTRA 1250/1650/2450 | \$ 13.301 |
| 56P1139 | TARJETA LEXMARK T522/T522N | \$ 69.961 |
| AGP0202 | TARJETA VIDEO AGP 16 MB PINE | \$ 49.241 |
| SIS6326 | TARJETA VIDEO PCI 8 MB IDEMA | \$ 80.018 |
| RH7-7105-CLN | THERMISTOR HP LJ 8100 | \$ 21.804 |
| Q5949A | TONER HP LJ 1160/4320 | \$ 149.977 |
| 42127403 | TONER OKIDATA C5100/5150/5200/5300/5400 CYAN | \$ 152.586 |
| 42127402 | TONER OKIDATA C5100/5150/5200/5300/5400 MAGENTA | \$ 152.586 |
| 42127404 | TONER OKIDATA C5100/5150/5200/5300/5400 NEGRO | \$ 89.255 |
| 42127401 | TONER OKIDATA C5100/5150/5200/5300/5400 YELLOW | \$ 152.586 |
| RM1-0049-000 | TOP COVER ASSY HP LJ 4200/4300 SERIES | \$ 20.000 |
| RC1-0289-000 | TOP COVER REAR HP LJ 4200 | \$ 10.000 |
| 1410881 | TPE HOLDER ASY DFX 9000 "570" | \$ 67.878 |
| PJYE2P1592M1 | TRACTOR DERECHO PANASONIC KXP 1595 | \$ 39.165 |
| PJYE2P1624M1 | TRACTOR DERECHO PANASONIC KXP 3696 | \$ 30.120 |
| 1016339 | TRACTOR IZQUIERDO EPSON LQ 1070+/LX 810 | \$ 9.573 |
| F353253040 | TRACTOR IZQUIERDO EPSON LX 810/LQ 1070 | \$ 8.804 |
| PJYE1P1624M1 | TRACTOR IZQUIERDO PANASONIC KXP 3696 | \$ 15.000 |
| 1410875 | TRACTOR POST.IZQUIERDO EPSON DFX 9000 | \$ 125.802 |
| HPC3968A | TRANSFER BELT ASSY HP LJ 5/5M | \$ 421.540 |
| 2022418 | TRANSISTOR FET REF.K1482 EPSON FX 1180 (Q31) | \$ 11.609 |
| 2011458 | TRANSISTOR FET REF.K1692 EPSON DFX 8500 (QF201) | \$ 64.806 |
| 2025431 | TRANSISTOR FET REF.K2611 EPSON DFX 8500 (QF101) | \$ 29.625 |
| 2023652 | TRANSISTOR FET REF.K2662 EPSON FX 1180 (Q1) | \$ 25.160 |
| IRFP250 | TRANSISTOR FUENTE HP CLR LJ 8150 | \$ 9.940 |
| C2655 | TRANSISTOR FUENTE REF.C2655 EPSON DFX 8000 | \$ 2.862 |
| C4927 | TRANSISTOR MONITOR REF. C4927 HORIZONTAL | \$ 10.970 |
| AN5534 | TRANSISTOR MONITOR REF.AN5534 VERTICAL | \$ 10.345 |
| BU2708AF | TRANSISTOR MONITOR REF.BU2708AF HORIZONTAL | \$ 2.428 |



PARTES NUEVAS

| Código | Descripcion | PRECIO |
|--------------|--|------------|
| C3997 | TRANSISTOR MONITOR REF.C3997 HORIZONTAL | \$ 9.762 |
| C5297 | TRANSISTOR MONITOR REF.C5297 HORIZONTAL | \$ 3.103 |
| C5411 | TRANSISTOR MONITOR REF.C5411 HORIZONTAL | \$ 6.988 |
| C5449 | TRANSISTOR MONITOR REF.C5448 HORIZONTAL | \$ 12.941 |
| C5802 | TRANSISTOR MONITOR REF.C5802 HORIZONTAL | \$ 21.551 |
| C5929 | TRANSISTOR MONITOR REF.C5929 HORIZONTAL | \$ 11.206 |
| IRF630 | TRANSISTOR MONITOR REF.IRF630 FET | \$ 5.280 |
| TRANSISTORES | TRANSISTOR MONITOR REF.J449 | \$ 1.231 |
| STV9302A | TRANSISTOR MONITOR REF.STV9302A VERTICAL | \$ 8.620 |
| TDA1675 | TRANSISTOR MONITOR REF.TDA1675 VERTICAL | \$ 3.908 |
| TDA4856 | TRANSISTOR MONITOR REF.TDA4856 | \$ 3.448 |
| TDA4859PS | TRANSISTOR MONITOR REF.TDA4859 | \$ 12.931 |
| BU2508AF | TRANSISTOR REF BU2508AF | \$ 6.896 |
| 2S0680 | TRANSISTOR REF.2S0680 | \$ 17.241 |
| X44074319 | TRANSISTOR REF.431L EPSON DFX 8500 (IC201) | \$ 9.099 |
| 2024544 | TRANSISTOR REF.78L05 EPSON DFX 8500 (IC202) | \$ 6.479 |
| 2000623 | TRANSISTOR REF.C4408 EPSON DFX 8500 (Q201) | \$ 14.812 |
| 2013170 | TRANSISTOR REF.C5060 EPSON LX 300 | \$ 1.667 |
| 2020004 | TRANSISTOR REF.K1398 EPSON DFX 8500 (QF102) | \$ 6.479 |
| 12G0029 | TRAY 1 FRON EXIT LEXMARK 4044 OPTRA E310/312 | \$ 13.094 |
| RG5-2785-000 | TRAY 1 MULTI-PORPUSE HP LJ 6P/6MP | \$ 61.085 |
| RC1-2018-000 | TRAY 2 CASSETTE HP LJ 1020 | \$ 2.897 |
| C9915-60003 | TRAY ASSY, PAPER INPUT HP SCJ 5590/8200 | \$ 36.215 |
| RM1-1486-000 | TRAY CASSETTE HP LJ 2400 (250 SHEET) | \$ 79.416 |
| C8056A | TRAY CASSETTE HP LJ 4000/4050/4100 (500 SHEET) | \$ 618.114 |
| RG5-3552-000 | TRAY FACE-UP ASSY HP LJ 5000/5100 SERIES | \$ 51.818 |
| BCR10CM | TRIAC FUENTE EPSON DFX 8000 | \$ 5.534 |
| 1261641 | UNIDAD TRACTOR EPSON FX 2190 (VER 1408792) | \$ 38.000 |
| 1013479 | UNIDAD TRACTOR EPSON LQ 1070/1070+ | \$ 50.480 |
| 2081380 | VENTILADOR EPSON FX 2190 | \$ 1.277 |
| 1018949-2 | VISOR RIBBON MASK EPSON DFX 5000+ | \$ 3.136 |
| 99A0292B | WEAR STRIP LEXMARK OPTRA S | \$ 5.700 |
| 99A0292 | WEAR STRIP LEXMARK OPTRA S | \$ 2.850 |
| 99A0123 | WEAR STRIP LEXMARK OPTRA S | \$ 3.230 |
| CVR-4200-L | WIRE HOLDER LEFT HP LJ 4200 | \$ 24.408 |
| CVR-4200-R | WIRE HOLDER RIGHT HP LJ 4200 | \$ 7.084 |

PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|--|-----------|
| ADAP6V-1 | ADAPTADOR 6 V HITRON | \$ 10.000 |
| ADAP9V-1 | ADAPTADOR 9 V | \$ 10.000 |
| C825321-1 | ADAPTADOR EPSON TM 675 | \$ 10.000 |
| 2008593-1 | ADAPTADOR EPSON TMU 200/300 | \$ 50.000 |
| ADAP30V-1 | ADAPTADOR LEXMARK 30V | \$ 15.000 |
| RB2-3001-1 | BANDEJA AUTOMATICA HP LJ 2100/2200 (TRAY 2) | \$ 15.000 |
| RG5-5580-1 | BANDEJA AUTOMATICA HP LJ 2200 (250 SHEET) | \$ 15.000 |
| C2084A-1 | BANDEJA AUTOMATICA HP LJ 4/4M/4+ (TRAY 2) | \$ 15.000 |
| R75-0010-1 | BANDEJA AUTOMATICA HP LJ 4L/4LM (TRAY 2) | \$ 15.000 |
| RB1-3335-1 | BANDEJA AUTOMATICA HP LJ 4P (TRAY 2) | \$ 15.000 |
| RB1-6377-1 | BANDEJA AUTOMATICA HP LJ 5 (TRAY 2) | \$ 15.000 |
| R75-4000-1 | BANDEJA AUTOMATICA HP LJ 5P/5MP (TRAY 2) | \$ 20.000 |
| R98-0004-1 | BANDEJA AUTOMATICA HP LJ 8000/8100/8150 (TRAY 3) | \$ 60.000 |
| RG5-4601-1 | BANDEJA ENTRADA HP LJ 1100 | \$ 7.000 |
| RG5-1945-1 | BANDEJA ENTRADA HP LJ 5L | \$ 5.000 |
| F338554000-1 | BANDEJA EPSON FX 1050 | \$ 10.000 |
| 1025029-1 | BANDEJA EPSON FX/LQ 2170 | \$ 15.000 |
| F359654000-1 | BANDEJA EPSON LX 810 | \$ 15.000 |
| C2164-67808-1 | BANDEJA HP DJ 600 SERIES (SALIDA) | \$ 5.000 |
| C2164-00656-1 | BANDEJA HP DJ 656 (SALIDA) | \$ 5.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|----------------|---|------------|
| C2060-00600-1 | BANDEJA INTERNA HP DJ 600 SERIES | \$ 5.000 |
| RG5-2785-1 | BANDEJA MANUAL HP LJ 6P/6MP (TRAY 1) | \$ 15.000 |
| PJKK159Z-1 | BANDEJA PANASONIC KXP 3696 #2 | \$ 15.000 |
| RB1-8843-1 | BANDEJA POSTERIOR HP LJ 4000/4050 | \$ 20.000 |
| F346208000 | BOARD ASSY HEAD EPSON DFX 5000/8000 (3 CONECT) | \$ 5.000 |
| 2000718-1 | BOARD ASSY HEAD EPSON DFX 5000/8000 (3 CONECT) | \$ 5.000 |
| 2023805-1 | BOARD C204DRV-B EPSON DFX 8500 | \$ 20.000 |
| QH1-1138-000-1 | BOARD CARRIAGE CANON BJ 330 | \$ 5.000 |
| C5870-60017-1 | BOARD CARRIAGE HP DJ 710/720 | \$ 15.000 |
| C6409-80093-1 | BOARD CARRIAGE HP DJ 840 | \$ 5.000 |
| C4602-60040-1 | BOARD CARRIAGE HP DJ 890 | \$ 5.000 |
| 2023751-1 | BOARD CONECTOR SENSORA EPSON DFX 8500 | \$ 5.000 |
| 2000794-1 | BOARD CONECTOR TERMINAL EPSON DFX 8000/8500 | \$ 5.000 |
| RG0-1090-1 | BOARD CONNECTOR HP LJ 1000 | \$ 5.000 |
| RG5-0512-1 | BOARD CONTROL PAPER HP LJ 4/4+/5 (DETECTA TRAY 2) | \$ 10.000 |
| RG5-3560-1 | BOARD CONTROLLER FEEDER HP LJ 5000 | \$ 35.000 |
| RG0-1093-1 | BOARD CONTROLLER HP LJ 1000 SERIES | \$ 50.000 |
| RG5-4125-1 | BOARD CONTROLLER HP LJ 2100 | \$ 25.000 |
| RG5-5566-1 | BOARD CONTROLLER HP LJ 2200 | \$ 25.000 |
| RG1-4307-1 | BOARD CONTROLLER HP LJ 2300 | \$ 40.000 |
| RG5-0511-1 | BOARD CONTROLLER HP LJ 4 | \$ 15.000 |
| RG5-0966-1 | BOARD CONTROLLER HP LJ 4+/4M | \$ 15.000 |
| C4118-69009 | BOARD CONTROLLER HP LJ 4000/4050 | \$ 50.000 |
| C8049-69009 | BOARD CONTROLLER HP LJ 4100 SERIES | \$ 40.000 |
| RG1-4236-1 | BOARD CONTROLLER HP LJ 4200 SERIES | \$ 40.000 |
| RG5-1844-1 | BOARD CONTROLLER HP LJ 5SI/8000 | \$ 60.000 |
| RG1-1604-1 | BOARD DENSITY AJUST HP LJ IIP/IIIP (CANT.TONER) | \$ 10.000 |
| 2000114-1 | BOARD DRIVER EPSON DFX 8000 | \$ 50.000 |
| 2023803-1 | BOARD DRIVER EPSON DFX 8500 | \$ 50.000 |
| 2007522-1 | BOARD DRIVER EPSON TMU 300A/B/PB | \$ 50.000 |
| C823634-1 | BOARD INTERFACE EPSON DFX 5000+/8000/8500 | \$ 50.000 |
| 1046579-1 | BOARD INTERMEDIATE EPSON TMU 675 (708) | \$ 15.000 |
| 2009617-1 | BOARD MAIN EPSON ACTION 1500 | \$ 10.000 |
| 2011316-1 | BOARD MAIN EPSON DFX 5000+ | \$ 200.000 |
| 2000113-1 | BOARD MAIN EPSON DFX 8000 | \$ 160.000 |
| 2023797-1 | BOARD MAIN EPSON DFX 8500 | \$ 250.000 |
| 2004727-1 | BOARD MAIN EPSON EPL 8000 | \$ 10.000 |
| Y461201000-1 | BOARD MAIN EPSON FX 1050 | \$ 30.000 |
| Y461203000-1 | BOARD MAIN EPSON FX 850 | \$ 30.000 |
| 2006158-1 | BOARD MAIN EPSON FX 870 | \$ 40.000 |
| Y454201000-1 | BOARD MAIN EPSON LQ 1050 | \$ 30.000 |
| Y565201000-1 | BOARD MAIN EPSON LX 800 | \$ 20.000 |
| C1676-60102-1 | BOARD MAIN HP DJ 1200 | \$ 30.000 |
| C1676-61600-1 | BOARD MAIN HP DJ 1600 | \$ 30.000 |
| C2642-60204-1 | BOARD MAIN HP DJ 400 | \$ 30.000 |
| C6450-00656-1 | BOARD MAIN HP DJ 656 | \$ 20.000 |
| C2164-69001-1 | BOARD MAIN HP DJ 660 | \$ 20.000 |
| C4531-67808-1 | BOARD MAIN HP DJ 820/CXI | \$ 20.000 |
| C4555-69807-1 | BOARD MAIN HP DJ 870/CXI | \$ 20.000 |
| C7857-60001-1 | BOARD MAIN HP LJ 1200 | \$ 20.000 |
| C4209-61002-1 | BOARD MAIN HP LJ 2200 | \$ 70.000 |
| Q1395-60002-1 | BOARD MAIN HP LJ 2300 | \$ 80.000 |
| C2002-69001-1 | BOARD MAIN HP LJ 4 | \$ 40.000 |
| C2038-69004-1 | BOARD MAIN HP LJ 4+ | \$ 30.000 |
| C4118-67908-1 | BOARD MAIN HP LJ 4000/N/T | \$ 100.000 |
| C9652-69001 | BOARD MAIN HP LJ 4200 SERIES | \$ 150.000 |
| C2004-69001-1 | BOARD MAIN HP LJ 4L | \$ 30.000 |
| C2006-67901-1 | BOARD MAIN HP LJ 4P | \$ 30.000 |
| C3919-60001-1 | BOARD MAIN HP LJ 5 | \$ 30.000 |
| C3151-60001-1 | BOARD MAIN HP LJ 5P | \$ 30.000 |
| C3168-60001-1 | BOARD MAIN HP LJ 5SI VER.C3168-67906-1 | \$ 60.000 |




PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|----------------|--|-----------|
| C3981-69001-1 | BOARD MAIN HP LJ 6P/6MP | \$ 50.000 |
| 33497-67901-1 | BOARD MAIN HP LJ II/III | \$ 10.000 |
| 33471-60001-1 | BOARD MAIN HP LJ IIP/IIIP | \$ 10.000 |
| 17D0570-1 | BOARD MAIN LEXMARK 3200 | \$ 30.000 |
| 55081001-1 | BOARD MAIN OKIDATA 390T | \$ 50.000 |
| 55080502-1 | BOARD MAIN OKIDATA 4W | \$ 50.000 |
| 55072401-1 | BOARD MAIN OKIDATA 520/521 | \$ 50.000 |
| 55937401-1 | BOARD MAIN OKIDATA 590/591 | \$ 50.000 |
| PJUP571YA-1 | BOARD MAIN PANASONIC KXP 1121 | \$ 30.000 |
| PJWPP3696M-1 | BOARD MAIN PANASONIC KXP 3696 | \$ 30.000 |
| 2033545-1 | BOARD PANEL EPSON LX 300+ | \$ 5.000 |
| 2007520-1 | BOARD PANEL EPSON TM 300 | \$ 15.000 |
| 1046163-1 | BOARD PANEL EPSON TMU 675 (134) | \$ 10.000 |
| 55081103-1 | BOARD PANEL OKIDATA 320T/390T | \$ 10.000 |
| 2020560-1 | BOARD PARALLEL EPSON TMU 200PB/PD/220PA/PB/230P/300PD/675P | \$ 50.000 |
| 2019979-1 | BOARD SERIAL EPSON TMU 200A/B/D/325D/590/675/P | \$ 80.000 |
| 140810-1 | BOBINA CABEZA EPSON LX 810 | \$ 3.000 |
| 2012927-1 | BUS DATOS BOARD INTERFACE EPSON LX 300 | \$ 1.000 |
| F338005020-1 | BUS DATOS EPSON FX 1050 | \$ 2.000 |
| 2026504-1 | BUS DATOS EPSON FX 1180/1180+ | \$ 2.000 |
| 2005610-1 | BUS DATOS EPSON FX 870 | \$ 2.000 |
| 2025259-1 | BUS DATOS EPSON FX 880 | \$ 2.000 |
| 2019015-1 | BUS DATOS EPSON FX/LQ 2170/2070/2180 SENSOR | \$ 2.000 |
| 2019013-1 | BUS DATOS EPSON FX/LQ 2170/2180 INF.ANC | \$ 2.000 |
| 2019014-1 | BUS DATOS EPSON FX/LQ 2170/2180 SUP.ANG | \$ 2.000 |
| 2003372-1 | BUS DATOS EPSON LQ 1070 FRON.ANC | \$ 2.000 |
| 2003373-1 | BUS DATOS EPSON LQ 1070 TRAS.ANG | \$ 2.000 |
| 2003026-1 | BUS DATOS EPSON LQ 1170 INF.ANC | \$ 2.000 |
| 2003027-1 | BUS DATOS EPSON LQ 1170 SUP.ANG | \$ 2.000 |
| 2013002-1 | BUS DATOS EPSON LX 300 | \$ 2.000 |
| 1033488-1 | BUS DATOS EPSON STY 3000 COLOR LARGO | \$ 3.000 |
| 1033489-1 | BUS DATOS EPSON STY 3000 NEGRO CORTO | \$ 3.000 |
| 2014128-1 | BUS DATOS EPSON STY 500 NEGRO | \$ 1.000 |
| 2008871-1 | BUS DATOS EPSON STY 800 NEGRO | \$ 1.000 |
| C3540-60008-1 | BUS DATOS HP DJ 1600 | \$ 2.000 |
| C2124-80005-1 | BUS DATOS HP DJ 500 NEGRO | \$ 1.000 |
| C2145-60032-1 | BUS DATOS HP DJ 850/870/OFJ 1150 | \$ 1.000 |
| 56634001-1 | BUS DATOS OKIDATA 390T ANGOSTO | \$ 2.000 |
| 56627301-1 | BUS DATOS OKIDATA 520/521/590/591 | \$ 2.000 |
| PJJE1121-1 | BUS DATOS PANASONIC KXP 1121 | \$ 2.000 |
| PJJE338Z-1 | BUS DATOS PANASONIC KXP 3696 #1 | \$ 2.000 |
| PJW8887-1 | BUS DATOS PANASONIC KXP 3696 (X2 INTERFACE) | \$ 2.000 |
| RH2-5350-000-1 | BUS DATOS SCANNER HP LJ 2100 | \$ 15.000 |
| 4541210-1 | BUS PANEL CANON BJ 330 | \$ 2.000 |
| 2081151-1 | BUS PANEL EPSON FX 2190 | \$ 2.000 |
| 2018862-1 | BUS PANEL EPSON FX/LQ 2170/2070/2180 | \$ 2.000 |
| 2034843-1 | BUS PANEL EPSON LX 300+ | \$ 2.000 |
| 1026005-1 | BUS PANEL EPSON STY 1500 COLOR | \$ 2.000 |
| 1020132-1 | BUS PANEL EPSON STY 400 | \$ 2.000 |
| 2023343-1 | BUS PANEL EPSON STY 600/640 | \$ 2.000 |
| PJJ2896-1 | BUS PANEL PANASONIC KXP 1150 | \$ 2.000 |
| 2000026-1 | CABLE PANEL EPSON DFX 5/8/5+ | \$ 2.000 |
| 2024024-1 | CABLE PANEL EPSON DFX 8500 | \$ 2.000 |
| 2002859-1 | CABLE PANEL EPSON LQ 1070/1070+ | \$ 2.000 |
| Y456301000-1 | CABLE PANEL EPSON LQ 2550 | \$ 2.000 |
| 2002860-1 | CABLE PODER IMPRESORA | \$ 2.000 |
| RH2-5104-1 | CABLE SCANNER HP LJ IIP/IIIP | \$ 2.000 |
| 110403M-1 | CABLE SERIAL DE 3 MTS (M/M) | \$ 2.000 |
| RF5-1501-1 | CARCAZA FRONTAL HP LJ 5L/6L | \$ 5.000 |
| C4549-40001-1 | CARCAZA HP DJ 600 SERIES | \$ 2.000 |
| 1036534-1 | CARCAZA INFERIOR EPSON FX 880 | \$ 15.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|---|-----------|
| 1050623-1 | CARCAZA INFERIOR EPSON LX 300+ | \$ 15.000 |
| RF5-2828-1 | CARCAZA POSTERIOR HP LJ 1100 | \$ 10.000 |
| F338555020-1 | CARCAZA SUPERIOR EPSON FX 1050 | \$ 10.000 |
| 1036535-1 | CARCAZA SUPERIOR EPSON FX 880 | \$ 15.000 |
| 1018199-1 | CARCAZA SUPERIOR EPSON LX 300 | \$ 5.000 |
| F359652000-1 | CARCAZA SUPERIOR EPSON LX 810 | \$ 5.000 |
| 1033593-1 | CARCAZA SUPERIOR EPSON STY 3000 | \$ 5.000 |
| RG5-1995-1 | CARCAZA SUPERIOR HP LJ 5L/6L | \$ 10.000 |
| QG5-0125-1 | CARRIAGE CANON BJ 200 | \$ 5.000 |
| QH1-1138-1 | CARRIAGE CANON BJ 330 | \$ 5.000 |
| QB1-0800-1 | CARRIAGE CANON BJ 600/610 | \$ 5.000 |
| QB1-2916-1 | CARRIAGE CANON BJC 4300 | \$ 5.000 |
| F346201000-1 | CARRIAGE EPSON DFX 5000 | \$ 15.000 |
| 1000928-1 | CARRIAGE EPSON DFX 8000 | \$ 15.000 |
| 1033105-1 | CARRIAGE EPSON DFX 8500 | \$ 15.000 |
| 1237005-1 | CARRIAGE EPSON FX 2190 | \$ 10.000 |
| F344204000-1 | CARRIAGE EPSON LQ 2550 | \$ 10.000 |
| 1026414-1 | CARRIAGE EPSON TMU 200A/B/D/PB/PD/230/P | \$ 15.000 |
| 1046580-1 | CARRIAGE EPSON TMU 675 (709) | \$ 10.000 |
| C2113-60032-1 | CARRIAGE HP DJ 500 | \$ 5.000 |
| 53590402-1 | CARRIAGE OKIDATA 320/321 | \$ 15.000 |
| 53349801-1 | CARRIAGE OKIDATA 320T/321T/390T/391T | \$ 15.000 |
| 50098901-1 | CARRIAGE OKIDATA 520/521/590/591 | \$ 15.000 |
| 1018252-1 | CHASIS EPSON LX 300 | \$ 10.000 |
| F359001010-1 | CHASIS EPSON LX 810 | \$ 10.000 |
| C4562-60065-1 | CHASIS HP DJ 600 SERIES | \$ 10.000 |
| RG0-2200-1 | CHASIS HP LJ 2200 | \$ 25.000 |
| RB2-5000-1 | CHASIS HP LJ 4100 SERIES | \$ 35.000 |
| 1005220-1 | CLUTCH EPSON FX/LQ 1170/2170/1180/880 | \$ 2.000 |
| 1004919-1 | CLUTCH EPSON LQ 1070/1070+/570 | \$ 2.000 |
| C4555-01200-1 | CLUTCH HP DJ 1200/1600 | \$ 2.000 |
| C4557-40084-1 | CLUTCH HP DJ 710/720/810/840 PALANCA | \$ 2.000 |
| C4557-40040-1 | CLUTCH HP DJ 710/720/810/840 PINON | \$ 2.000 |
| RG5-4585-1 | CLUTCH HP LJ 1100/3200 | \$ 2.000 |
| RB2-3040-1 | CLUTCH HP LJ 2100 TRAY 1 | \$ 5.000 |
| RG5-5552-1 | CLUTCH HP LJ 2200 SOLENOIDE | \$ 5.000 |
| RH7-5192-1 | CLUTCH HP LJ 5000 | \$ 5.000 |
| RB1-7197-1 | CLUTCH HP LJ 5L/6L | \$ 2.000 |
| 1046279-1 | COIL, LEVER DRIVE A EPSON TMU 675 (621) | \$ 5.000 |
| 1046280-1 | COIL, LEVER DRIVE B EPSON TMU 675 (622) | \$ 5.000 |
| F344902000-1 | COLOR SELECT UNIT EPSON LQ 2550 | \$ 5.000 |
| QC1-0200-1 | CORREA CANON BJ 200E | \$ 5.000 |
| QC1-0250-1 | CORREA CANON BJ 250 | \$ 5.000 |
| QC1-0330-1 | CORREA CANON BJ 330 | \$ 5.000 |
| QC1-0600-1 | CORREA CANON BJ 600 | \$ 5.000 |
| QH4-1000-1 | CORREA CANON BJC 1000 | \$ 5.000 |
| QH4-4100-1 | CORREA CANON BJC 4100 | \$ 5.000 |
| F346003250-1 | CORREA EPSON DFX 5000/5000+/8000 | \$ 10.000 |
| 1000497-1 | CORREA EPSON DFX 5000/5000+/8000 CORTA | \$ 10.000 |
| F334005170-1 | CORREA EPSON FX 850 | \$ 5.000 |
| F344202000-1 | CORREA EPSON LQ 2550 | \$ 5.000 |
| 1014497-1 | CORREA EPSON STY 1000 | \$ 10.000 |
| 1026004-1 | CORREA EPSON STY 1520 | \$ 10.000 |
| 1033487-1 | CORREA EPSON STY 3000 | \$ 10.000 |
| 1013882-1 | CORREA EPSON STY 400/600/640/PHOTO | \$ 5.000 |
| 1023301-1 | CORREA EPSON STY 500 | \$ 2.000 |
| 1014180-1 | CORREA EPSON STY II COLOR | \$ 2.000 |
| 1024047-1 | CORREA EPSON STY IIS COLOR | \$ 2.000 |
| 1046301-1 | CORREA EPSON TMU 675 (629) | \$ 2.000 |
| C2642-60216-1 | CORREA HP DJ 400/420 | \$ 5.000 |
| C2106-40012-1 | CORREA HP DJ 500 SERIES | \$ 5.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|--|------------|
| C2145-40058-1 | CORREA HP DJ 820/850/870/890 | \$ 5.000 |
| C2124-11150 | CORREA HP OFJ 1150 | \$ 5.000 |
| C2124-11150-1 | CORREA HP OFJ 1150 | \$ 5.000 |
| C2124-01150-1 | CORREA HP OFJ 1150 SCANNER | \$ 5.000 |
| 53489402-1 | CORREA OKIDAT 320/321/320T/390T | \$ 5.000 |
| 53563401-1 | CORREA OKIDATA 520/521/590/591 | \$ 5.000 |
| PJN01150-1 | CORREA PANASONIC KXP 1150 | \$ 5.000 |
| PJN01182-1 | CORREA PANASONIC KXP 1180 | \$ 5.000 |
| PJJNW3152-1 | CORREA PANASONIC KXP 3696 | \$ 5.000 |
| RM1-0050-1 | COVER ASSY, FRONT HP LJ 4200/4300 SERIES | \$ 15.000 |
| RC1-0287-1 | COVER ASSY, LEFT HP LJ 4200 | \$ 25.000 |
| RM1-0046-1 | COVER ASSY, RIGHT HP LJ 4200 | \$ 25.000 |
| RG5-3550-1 | COVER SIDE LEFT HP LJ 5000 | \$ 25.000 |
| RB2-1749-1 | COVER SIDE RIGHT HP LJ 5000/5100 SERIES | \$ 25.000 |
| 1046548-1 | DETECTOR ASSY FRONT COVER EPSON TMU 675 (691) | \$ 10.000 |
| 1046549-1 | DETECTOR ASSY REAR COVER EPSON TMU 675 (692) | \$ 10.000 |
| 1046578-1 | DETECTOR H.P. ASSY EPSON TMU 675 (707) | \$ 10.000 |
| 1046547-1 | DETECTOR PAPER EJECT EPSON TMU 675 (690) | \$ 10.000 |
| 1046557-1 | DETECTOR VALIDATION ASSY EPSON TMU 675 (697) | \$ 10.000 |
| 25L2577-1 | DISCO DURO PORTATIL 4.3 GB | \$ 10.000 |
| C4782-60501-1 | DUPLEX HP LJ 8000/8100/8150 | \$ 120.000 |
| F338005010-1 | EJE CARRO EPSON FX 1050 | \$ 8.000 |
| 1038497-1 | EJE CARRO EPSON FX 1180 | \$ 8.000 |
| 1265406-1 | EJE CARRO EPSON FX 2190 | \$ 10.000 |
| 1008698-1 | EJE CARRO EPSON FX 870/880 | \$ 10.000 |
| 1050431-1 | EJE CARRO EPSON LX 300+ | \$ 10.000 |
| F353003010-1 | EJE CARRO EPSON LX 810 | \$ 10.000 |
| C2642-80021-1 | ENCODER HP DJ 400/420 | \$ 5.000 |
| C2145-80016-1 | ENCODER HP DJ 820/850/855/870/890/OFJ 1150/1170/1175 | \$ 5.000 |
| RG5-0667-1 | ESPEJO HP LJ 4L | \$ 5.000 |
| RG5-0802-1 | ESPEJO HP LJ 4P | \$ 5.000 |
| RG5-1786-1 | ESPEJO HP LJ 5P/6P | \$ 5.000 |
| RG1-1772-1 | ESPEJO SCANNER HP LJ IIP/IIIP | \$ 5.000 |
| 1039413-1 | FRAME PAPER EJECT LEFT EPSON FX 2180 | \$ 3.000 |
| 1025303-1 | FRAME PAPER EJECT RIGHT EPSON FX/LQ 2170/ 2180 | \$ 3.000 |
| 1005246-1 | FRAME TR, LEFT EPSON FX 1170/1180 | \$ 3.000 |
| 1004941-1 | FRAME TR, LEFT EPSON LQ 1070/1070+ | \$ 3.000 |
| 1018189-1 | FRAME TR, LEFT EPSON LX 300 | \$ 3.000 |
| F353253020-1 | FRAME TR, LEFT EPSON LX 810 | \$ 3.000 |
| 1013376-1 | FRAME TR, RIGHT EPSON LQ 1070/1070+ | \$ 3.000 |
| 1046307-1 | GEAR CARRIAGE DRIVE TRANSMISSION EPSON TMU 675 (634) | \$ 3.000 |
| 1046259-1 | GEAR LEVER DRIVE SHAFT EPSON TMU 675 (617) | \$ 3.000 |
| 1046415-1 | GEAR RIBBON INTERMEDIATE EPSON TMU 675 (683) | \$ 3.000 |
| 1046413-1 | GEAR RIBBON REDUCTION EPSON TMU 675 (682) | \$ 3.000 |
| 1046587-1 | GEAR RIBBON TAKE-UP EPSON TMU 675 (712) | \$ 3.000 |
| RS5-0695 -1 | GEAR SHAFT DRIVE HP LJ 5000 | \$ 5.000 |
| 1277106-1 | GUIA PAPEL EPSON FX 2190 | \$ 5.000 |
| F353254010-1 | GUIA PAPEL EPSON LX 810 (SIN ACRILICO) | \$ 3.000 |
| 1265824-1 | GUIA PAPEL INF. EPSON FX 2190 | \$ 5.000 |
| 1005151-1 | GUIA PAPEL INF. EPSON FX 870 | \$ 5.000 |
| 1005213-1 | GUIA PAPEL INF. EPSON FX 880 | \$ 5.000 |
| F353251010-1 | GUIA PAPEL INF. EPSON LX 810 | \$ 5.000 |
| 53350101-1 | GUIA PAPEL OKIDATA 320T/390T | \$ 5.000 |
| 53355201-1 | GUIA PAPEL OKIDATA 520/521 | \$ 5.000 |
| RF5-1530-1 | GUIA ROLLER TRANSFER HP LJ 5L/6L | \$ 5.000 |
| RB2-1774-1 | GUIDE CARTRIDGE LEFT HP LJ 5000 | \$ 5.000 |
| RB2-1775-1 | GUIDE CARTRIDGE RIGHT HP LJ 5000 | \$ 5.000 |
| RG0-1022-1 | GUIDE FRONT ASSY HP LJ 1200/1000 | \$ 5.000 |
| C4549-60043-1 | GUIDE PAPER HP DJ 600 SERIES (METALICA) | \$ 2.000 |
| C4555-40005-1 | GUIDE PAPER HP DJ 820/870/890 (LOWER) | \$ 2.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|---|-----------|
| C6429-60141-1 | GUIDE PAPER INNER HP DJ 930/950/970/OFJ G55 | \$ 2.000 |
| C6426-40098-1 | GUIDE PAPER LOWER HP DJ 930/950/970 | \$ 2.000 |
| RG5-5548-1 | GUIDE REVERSE ASSY HP LJ 2200/2300 SERIES | \$ 10.000 |
| RG5-2013-1 | GUIDE SEPARATION ASSY HP LJ 5L | \$ 5.000 |
| RB2-3041-1 | HINGE LEFT HP LJ 2100/2200 -TRAY 1 | \$ 5.000 |
| RB2-3042-1 | HINGE RIGHT HP LJ 2100/2200 -TRAY 1 | \$ 5.000 |
| RB2-6406-1 | HINGE RIGHT HP LJ 2300 SERIES -TRAY 1 | \$ 5.000 |
| 1005182-1 | HOLDER EPSON FX 1170/FX 1180/FX 2190 | \$ 5.000 |
| 1017361-1 | HOLDER SLIP PAPER INSERTION DETECT EPSON TMU 675 (606) | \$ 5.000 |
| 211009-02 | INTEGRADO REF.211009-02 | \$ 2.000 |
| J3113-61001-1 | JET DIRECT HP LJ 4000/4050/2100/5000/8000 (600N) | \$ 70.000 |
| J2552-69013 | JET DIRECT HP LJ 4M+/4V/DJ 1200/1600/2500/DSJ 600/700/750 | \$ 70.000 |
| 1008688-D | KIT PIÑONES EPSON FX 1170/1180 | \$ 7.000 |
| 1049976-1 | KIT PIÑONES EPSON FX/LQ 2170/2070/2180 | \$ 15.000 |
| 1002296-1 | KIT PIÑONES EPSON LX 300/LX 300+ | \$ 6.000 |
| Y412303002-1 | KIT PIÑONES EPSON MX 100 | \$ 5.000 |
| 1000300-2 | KIT PIÑONES EPSON TM 300 | \$ 5.000 |
| 51238801-1 | KIT PIÑONES OKIDATA 320T/321T/390T/391T | \$ 5.000 |
| 51228501-1 | KIT PIÑONES OKIDATA 520/521/590/591 | \$ 5.000 |
| QA2-0080-1 | KIT PIÑONES PALANCA CANON BJ 330 | \$ 5.000 |
| K200880-1 | KIT PIÑONES PALANCA EPSON FX 1170/1180/880 | \$ 5.000 |
| 51216101-1 | KIT PIÑONES PALANCA OKIDATA 320/321 (* 3) | \$ 5.000 |
| PJKT1121-1 | KIT PIÑONES PANASONIC KXP 1121 | \$ 5.000 |
| QA2-0038-1 | KIT PIÑONES RODILLO CANON BJ 330 | \$ 5.000 |
| 1000932-1 | LAMINA GUIA EPSON DFX 8000/5000+/8500 | \$ 10.000 |
| F315062020-1 | LAMINA GUIA EPSON FX 1050 | \$ 5.000 |
| 1005199-1 | LAMINA GUIA EPSON FX 1170/1180 | \$ 2.000 |
| 1014603-1 | LAMINA GUIA EPSON FX 1180/1170 | \$ 2.000 |
| F334005210-1 | LAMINA GUIA EPSON FX 850 | \$ 2.000 |
| 1086020-1 | LAMINA GUIA EPSON FX 870/880 | \$ 2.000 |
| F344003190-1 | LAMINA GUIA EPSON LQ 2550 | \$ 2.000 |
| 1018176-1 | LAMINA GUIA EPSON LX 300 | \$ 2.000 |
| 1004893-1 | LATERAL DERECHO EPSON LQ 1070/1070+ | \$ 10.000 |
| 1046574-1 | LEVER MOTOR T.P DETECT ASSY EPSON TMU 675 | \$ 5.000 |
| RM1-0334-1 | MAIN DRIVE ASSY HP LJ 2300 SERIES (PLATINA) | \$ 20.000 |
| RG5-5087-1 | MAIN DRIVE ASSY HP LJ 4100 SERIES | \$ 35.000 |
| RM1-0001-1 | MAIN DRIVE GEAR ASSY HP LJ 4200/4300 SERIES | \$ 40.000 |
| RG5-2672-1 | MECANISMO BANDEJA TRAY 2 HP LJ 4000/4050 | \$ 35.000 |
| C3938A-1 | MEMORIA HP LJ 5L/6L (2MB) | \$ 10.000 |
| QH4-4039-1 | MOTOR CARRIAGE CANON BJ 200E | \$ 5.000 |
| QH4-4112-1 | MOTOR CARRIAGE CANON BJ 210S/210SP/240 | \$ 5.000 |
| QH3-M55SP-1 | MOTOR CARRIAGE CANON BJ 330 | \$ 5.000 |
| QH4-4252-1 | MOTOR CARRIAGE CANON BJC 1000 | \$ 5.000 |
| QH4-4181-1 | MOTOR CARRIAGE CANON BJC 255SP | \$ 5.000 |
| QH4-4033-1 | MOTOR CARRIAGE CANON BJC 600 | \$ 5.000 |
| 2011558-1 | MOTOR CARRIAGE EPSON DFX 5000+ | \$ 5.000 |
| F337052000-1 | MOTOR CARRIAGE EPSON FX 1050/850 | \$ 5.000 |
| 2035035-1 | MOTOR CARRIAGE EPSON FX 2190/1180+/880+/890/LQ 2090/590 | \$ 10.000 |
| 2002936-1 | MOTOR CARRIAGE EPSON LQ 1070/570 | \$ 10.000 |
| F344201000-1 | MOTOR CARRIAGE EPSON LQ 2550 | \$ 10.000 |
| 2024147-1 | MOTOR CARRIAGE EPSON STY 3000 | \$ 10.000 |
| 2024654-1 | MOTOR CARRIAGE EPSON STY 400/600/PHOTO | \$ 10.000 |
| 2023615-1 | MOTOR CARRIAGE EPSON STY CLR 1520 | \$ 10.000 |
| 2011767-1 | MOTOR CARRIAGE EPSON STY CLR 300 | \$ 10.000 |
| 2017343-1 | MOTOR CARRIAGE EPSON STY CLR 500 | \$ 10.000 |
| 2017756-1 | MOTOR CARRIAGE EPSON STY CLR IIS | \$ 10.000 |
| 1014462-1 | MOTOR CARRIAGE EPSON TM 300 | \$ 15.000 |
| 2030904-1 | MOTOR CARRIAGE EPSON TMU 675 (733) | \$ 15.000 |
| RG5-61600-1 | MOTOR CARRIAGE HP DJ 1600C/CM/CN | \$ 10.000 |
| C2642-60221-1 | MOTOR CARRIAGE HP DJ 400/420 | \$ 10.000 |
| C6464-60002-1 | MOTOR CARRIAGE HP DJ 640C/642C/648C | \$ 10.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|--|-----------|
| C4557-60003-1 | MOTOR CARRIAGE HP DJ 710/720/810/840/OFJ R/T | \$ 10.000 |
| C4531-60012-1 | MOTOR CARRIAGE HP DJ 820/CXI/OFJ 1170C/1175 | \$ 10.000 |
| C2145-60011-1 | MOTOR CARRIAGE HP DJ 850C/855C/870C | \$ 10.000 |
| C4602-60022-1 | MOTOR CARRIAGE HP DJ 890/OFJ 1170C/1175C | \$ 10.000 |
| PJJQ196Z-1 | MOTOR CARRIAGE PANASONIC KXP 3696 | \$ 10.000 |
| RH7-1588-1 | MOTOR DC HP LJ 2300 | \$ 10.000 |
| 1046516-1 | MOTOR LEVER DRIVE ASSY EPSON TMU 675 (686) | \$ 15.000 |
| 56507003-1 | MOTOR LINE FEED OKIDATA 320/321/390/391 | \$ 15.000 |
| 56510302-1 | MOTOR LINE FEED OKIDATA 520/521 | \$ 15.000 |
| 56510301-1 | MOTOR LINE FEED OKIDATA 590/591 | \$ 15.000 |
| RH7-1404-1 | MOTOR MAIN DRIVE ASSY HP LJ 1100/3200 | \$ 15.000 |
| 2009928-1 | MOTOR MAIN EPSON ACTION LASER 1500 | \$ 15.000 |
| 2027740-1 | MOTOR MAIN EPSON EPL 8000 | \$ 15.000 |
| RH7-1381-1 | MOTOR MAIN HP LJ 2100 | \$ 10.000 |
| RH7-1458-1 | MOTOR MAIN HP LJ 2200 | \$ 20.000 |
| RH7-1460-1 | MOTOR MAIN HP LJ 2200 | \$ 15.000 |
| RH7-1152-1 | MOTOR MAIN HP LJ 4/4M | \$ 10.000 |
| RH7-1301-1 | MOTOR MAIN HP LJ 4+/4M+/5/5M | \$ 10.000 |
| RH7-1331-1 | MOTOR MAIN HP LJ 4000/4050 | \$ 15.000 |
| RH7-1504-1 | MOTOR MAIN HP LJ 4100 SERIES | \$ 15.000 |
| RH7-1357-1 | MOTOR MAIN HP LJ 5000 | \$ 20.000 |
| RH7-1282-1 | MOTOR MAIN HP LJ 5L | \$ 15.000 |
| 07BM-1504-1 | MOTOR MAIN HP LJ 5M COLOR | \$ 15.000 |
| RG5-1799-1 | MOTOR MAIN HP LJ 5P/5MP | \$ 15.000 |
| RH7-1260-1 | MOTOR MAIN HP LJ 5SI/ 8000/ MOPIER 240 | \$ 15.000 |
| RH7-1320-1 | MOTOR MAIN HP LJ 6L | \$ 10.000 |
| RG5-2786-1 | MOTOR MAIN HP LJ 6P/6MP | \$ 10.000 |
| RH7-1094-1 | MOTOR MAIN HP LJ IIP/IIP+/IIIP | \$ 10.000 |
| PJJQ204Z-1 | MOTOR MAIN PANASONIC KXP 6100/6500 | \$ 10.000 |
| RH7-1505-1 | MOTOR MAIN STEPPER HP LJ 1000 | \$ 10.000 |
| RH7-1473-1 | MOTOR MAIN STEPPER HP LJ 1200/1220/3330 | \$ 10.000 |
| C4557-60018-1 | MOTOR PAPER DRIVE HP DJ 710/720/810/840 | \$ 10.000 |
| C4531-60015-1 | MOTOR PAPER DRIVE HP DJ 820/CXI | \$ 10.000 |
| C2145-60010-1 | MOTOR PAPER DRIVE HP DJ 850C/855C | \$ 10.000 |
| C4555-60005-1 | MOTOR PAPER DRIVE HP DJ 870/CXI/OFJ 1150 | \$ 10.000 |
| C4602-60004-1 | MOTOR PAPER DRIVE HP DJ 890/CXI/OFJ 1170/1175 | \$ 10.000 |
| F346056000-1 | MOTOR PAPER FEED EPSON DFX 5000/8000/5000+ | \$ 15.000 |
| F337005070-1 | MOTOR PAPER FEED EPSON FX 1050/850 | \$ 15.000 |
| 2026522-1 | MOTOR PAPER FEED EPSON FX 1180 | \$ 15.000 |
| 2019040-1 | MOTOR PAPER FEED EPSON FX 2170 | \$ 15.000 |
| 2056298-1 | MOTOR PAPER FEED EPSON FX 2190/1180+/880+/890/LQ 590 | \$ 20.000 |
| 2025266-1 | MOTOR PAPER FEED EPSON FX 880 | \$ 20.000 |
| 2012448-1 | MOTOR PAPER FEED EPSON LQ 1070/570 | \$ 15.000 |
| 2003041-1 | MOTOR PAPER FEED EPSON LQ 1170/1170+ | \$ 15.000 |
| 2019034-1 | MOTOR PAPER FEED EPSON LQ 2070/2170 | \$ 15.000 |
| F359002030-1 | MOTOR PAPER FEED EPSON LX 810 | \$ 15.000 |
| 2023971-1 | MOTOR PAPER FEED EPSON STY CLR 3000 | \$ 10.000 |
| 2030928-1 | MOTOR PAPER FEED EPSON TMU 675 (739) | \$ 20.000 |
| Z53L6124-1 | MOTOR PAPER FEED LEXMARK Z53 | \$ 10.000 |
| PJJQ972AL-1 | MOTOR PAPER FEED PANASONIC KXP 1124 | \$ 5.000 |
| PJJQ182ZA-1 | MOTOR PAPER FEED PANASONIC KXP 1150/1121 | \$ 5.000 |
| PJJQ552B-1 | MOTOR PAPER FEED PANASONIC KXP 1595 | \$ 5.000 |
| P55Q1152AP-1 | MOTOR PAPER FEED PANASONIC KXP 1695 | \$ 5.000 |
| PJJQ115Z-1 | MOTOR PAPER FEED PANASONIC KXP 3696 | \$ 5.000 |
| C3540-60030-1 | MOTOR PAPER PICKUP HP DJ 1600C/CLR COPIER 210 | \$ 5.000 |
| C2164-60045-1 | MOTOR PAPER STEPPER HP DJ 600 SERIES | \$ 5.000 |
| 2025899-1 | MOTOR PLATEN GAP EPSON DFX 8500 | \$ 15.000 |
| F344214000-1 | MOTOR PLATEN GAP EPSON LQ 2550 | \$ 10.000 |
| RH7-1461-1 | MOTOR REVERSE HP LJ 2200 SERIES/2430N | \$ 15.000 |
| C3911-01126 | MOTOR SCANNER ASSY HP OFJ 1150C/1170C | \$ 15.000 |
| C3911-01126-1 | MOTOR SCANNER ASSY HP OFJ 1150C/1170C | \$ 15.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|--|-----------|
| RG1-1769-1 | MOTOR SCANNER HP LJ IIP/IIIP | \$ 10.000 |
| C4531-60016-1 | MOTOR SERVICE STATION HP DJ 820/CXI | \$ 10.000 |
| C2145-60012-1 | MOTOR SERVICE STATION HP DJ 850C/CXI/870C/CXI/OFJ PRO 1150 | \$ 10.000 |
| C5876-60066-1 | MOTOR SERVICE STATION HP DJ 890C/CXI/OFJ 1170C/1175C | \$ 10.000 |
| 56513701-1 | MOTOR SPACE OKIDATA 320T | \$ 15.000 |
| 56513901-1 | MOTOR SPACE OKIDATA 390T | \$ 10.000 |
| 07BM-1552-1 | MOTOR TAPA SUPERIOR HP LJ 5M COLOR | \$ 10.000 |
| 1046355-1 | MOUNTING PLATE,J/S SOLENOID EPSON TMU 675 (774) | \$ 10.000 |
| F334005390-1 | PALANCA ACER. CABEZA EPSON FX 1050 | \$ 3.000 |
| 1036494-1 | PALANCA ACER. CABEZA EPSON FX 1180 | \$ 3.000 |
| 1002047-1 | PALANCA ACER. CABEZA EPSON FX/LQ 2170/2070 | \$ 3.000 |
| F353003020-1 | PALANCA ACER. CABEZA EPSON LX 810 | \$ 3.000 |
| 1031874-1 | PALANCA ACER. CABEZA EPSON STY 1520 | \$ 2.000 |
| 2025600-1 | PALANCA ACER. CABEZA EPSON STY 300 | \$ 2.000 |
| 2025560-1 | PALANCA ACER. CABEZA EPSON STY 400/500/600/640 | \$ 2.000 |
| 2025014-1 | PALANCA ACER. CABEZA EPSON STY II COLOR | \$ 2.000 |
| C2642-60226-1 | PALANCA ACER. CABEZA HP DJ 400 | \$ 2.000 |
| 5347791-1 | PALANCA ACER. CABEZA OKIDATA 390/321 | \$ 2.000 |
| PJUB104Z-1 | PALANCA ACER. CABEZA PANASONIC KXP 1150/1121 | \$ 2.000 |
| PJUB72ZA-1 | PALANCA ACER. CABEZA PANASONIC KXP 1180 | \$ 2.000 |
| PJUB77ZA-1 | PALANCA ACER. CABEZA PANASONIC KXP 1695 | \$ 2.000 |
| PJUB111ZA-1 | PALANCA ACER. CABEZA PANASONIC KXP 3696 | \$ 2.000 |
| 02276-40125-1 | PALANCA ESTACION SERV. HP DJ 500 | \$ 2.000 |
| QH2-4134-1 | PALANCA PAPEL CANON BJ 200E | \$ 2.000 |
| QA2-0076-1 | PALANCA PAPEL CANON BJ 330 | \$ 2.000 |
| 1039410-1 | PALANCA PAPEL EPSON FX 2180 | \$ 2.000 |
| 1025361-1 | PALANCA PAPEL EPSON FX/LQ 2170 | \$ 2.000 |
| 1004917-1 | PALANCA PAPEL EPSON LQ 1070/1070+/570 | \$ 2.000 |
| 1018169-1 | PALANCA PAPEL EPSON LX 300 | \$ 2.000 |
| 2025300-1 | PALANCA PAPEL EPSON STY 300 (BANDEJA) | \$ 2.000 |
| 1711211-1 | PALANCA PAPEL EPSON STY 500 | \$ 2.000 |
| C2642-60233-1 | PALANCA PAPEL HP DJ 400/420 | \$ 2.000 |
| 1002223-1 | PALANCA PAPEL IBM 2331 | \$ 2.000 |
| 53489501-1 | PALANCA PAPEL OKIDATA 320/321/390/391 | \$ 2.000 |
| 50805101-1 | PALANCA PAPEL OKIDATA 520/521/590/591 | \$ 2.000 |
| PJUB74ZB-1 | PALANCA PAPEL PANASONIC KXP 1180 | \$ 2.000 |
| PJUB37ZB-1 | PALANCA PAPEL PANASONIC KXP 1595 | \$ 2.000 |
| 53377801-1 | PALANCA PISAPAPEL OKIDATA 321 | \$ 2.000 |
| PJUB73ZA-1 | PALANCA PISAPAPEL PANASONIC KXP 1180 | \$ 2.000 |
| 1030410-1 | PALANCA SENSORA EPSON STY 400/600/640 | \$ 2.000 |
| RB1-5939-1 | PALANCA SENSORA HP LJ 5P/6P (TRAY 1) | \$ 2.000 |
| RB1-6006-1 | PALANCA SENSORA HP LJ 5P/6P (TRAY 2) | \$ 2.000 |
| PJUPS3696-1 | PALANCA SENSORA PANASONIC KXP 3696 | \$ 2.000 |
| C2162-67813 | PALANCA SENSORA PAPEL HP DJ 660/670/680/690 | \$ 2.000 |
| C2145-40064 | PALANCA SENSORA PAPEL HP DJ 820/850/870/890/OFJ 1150 | \$ 2.000 |
| C2162-40152 | PALANCA SENSORA TAPA HP DJ 600 SERIES | \$ 2.000 |
| RB2-3989-1 | PALANCA SENSORA TAPA HP LJ 1100 (U. FUSORA) | \$ 2.000 |
| QB4-1350-1 | PANEL CONTROL CANON BJ 330 | \$ 5.000 |
| QH1-1205-1 | PANEL CONTROL CANON BJ 600 | \$ 5.000 |
| 2008934-1 | PANEL CONTROL EPSON ACTION 1500 | \$ 5.000 |
| F346559130-1 | PANEL CONTROL EPSON DFX 5000 | \$ 5.000 |
| 2011199-1 | PANEL CONTROL EPSON DFX 5000+ | \$ 5.000 |
| 2000789-1 | PANEL CONTROL EPSON DFX 8000 | \$ 5.000 |
| 2006171-1 | PANEL CONTROL EPSON EPL 8000 | \$ 5.000 |
| Y461510000-1 | PANEL CONTROL EPSON FX 1050 | \$ 5.000 |
| 1004782-1 | PANEL CONTROL EPSON LQ 1070/1070+/570/570+ | \$ 5.000 |
| 2003386-1 | PANEL CONTROL EPSON LQ 1070+ | \$ 5.000 |
| Y456501100-1 | PANEL CONTROL EPSON LQ 2550 | \$ 5.000 |
| 2009910-1 | PANEL CONTROL EPSON STY 1000 | \$ 5.000 |
| 2023495-1 | PANEL CONTROL EPSON STY 1520 | \$ 5.000 |
| 1033597-1 | PANEL CONTROL EPSON STY 3000 | \$ 5.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|--|-----------|
| 1032195-1 | PANEL CONTROL EPSON STY 400/600 | \$ 5.000 |
| 2023721-1 | PANEL CONTROL EPSON STY 500 | \$ 5.000 |
| 2024245-1 | PANEL CONTROL EPSON STY 800 CLR | \$ 5.000 |
| 2025684-1 | PANEL CONTROL EPSON STY II CLR | \$ 5.000 |
| 1032272-1 | PANEL CONTROL EPSON STY PHOTO | \$ 5.000 |
| C1576-01100-1 | PANEL CONTROL HP DJ 1100 | \$ 5.000 |
| C1676-60090-1 | PANEL CONTROL HP DJ 1200 | \$ 5.000 |
| C2642-80003-1 | PANEL CONTROL HP DJ 400 | \$ 5.000 |
| C2642-80042-1 | PANEL CONTROL HP DJ 420 | \$ 5.000 |
| C4557-60009-1 | PANEL CONTROL HP DJ 710/720/810/840/895 | \$ 5.000 |
| RG5-4608-1 | PANEL CONTROL HP LJ 1100 | \$ 5.000 |
| RG0-1024-1 | PANEL CONTROL HP LJ 1200 | \$ 5.000 |
| RH6-0226-1 | PANEL CONTROL HP LJ 2300 | \$ 15.000 |
| RG5-1077-1 | PANEL CONTROL HP LJ 4+/4M+ | \$ 5.000 |
| RG5-0816-1 | PANEL CONTROL HP LJ 4P | \$ 5.000 |
| RG5-2238-1 | PANEL CONTROL HP LJ 5/5M/5N | \$ 5.000 |
| RG5-5438-1 | PANEL CONTROL HP LJ 5000 | \$ 5.000 |
| RG5-2018-1 | PANEL CONTROL HP LJ 5L/6L | \$ 5.000 |
| 07BP-7001-1 | PANEL CONTROL HP LJ 5M COLOR | \$ 10.000 |
| RG1-1974-1 | PANEL CONTROL HP LJ III | \$ 5.000 |
| RH6-0010-1 | PANEL CONTROL HP LJ IIP/IIIP | \$ 5.000 |
| C4531-60017-1 | PANEL CONTROL LIGHT PIPE ASSY HP DJ 820/CXI/890/CXI | \$ 5.000 |
| C2145-60132-1 | PANEL CONTROL LIGHT PIPE ASSY HP DJ 850/855/870 | \$ 10.000 |
| 53562703-1 | PANEL CONTROL OKIDATA 520/521 | \$ 15.000 |
| 53562701-1 | PANEL CONTROL OKIDATA 590/591 | \$ 15.000 |
| RM1-0026-1 | PAPER DELIVERY OUTPUT ASSY HP LJ 4200/4300 SERIES | \$ 25.000 |
| 07BA-5005-1 | PAPER EXIT ASSY HP LJ 5M COLOR (MEC. SALIDA) | \$ 20.000 |
| RG0-1005-1 | PAPER FEED ASSY HP LJ 1200/1000 | \$ 15.000 |
| RM1-0025-1 | PAPER FEED BELT ASSY HP LJ 4200/4300 SERIES | \$ 15.000 |
| RG5-3526-1 | PAPER FEED BELT ASSY HP LJ 5000/ SOLO CORREAS | \$ 20.000 |
| RB1-7177-1 | PAPER FEED FRAME HP LJ 5L (MEC. ARRASTRE) | \$ 20.000 |
| RG5-5083-1 | PAPER FEED GUIDE HP LJ 4100 | \$ 20.000 |
| RG5-2192-1 | PAPER FEED GUIDE HP LJ 5 | \$ 10.000 |
| RG5-0456-1 | PAPER OUTPUT ASSY HP LJ 4 | \$ 10.000 |
| RG5-0451-1 | PAPER PICKUP ASSY HP LJ 4/5 (MEC. ARRASTRE) | \$ 20.000 |
| RG5-2655-1 | PAPER PICKUP ASSY HP LJ 4000/4050 | \$ 40.000 |
| RG5-5084-1 | PAPER PICKUP ASSY HP LJ 4100 | \$ 45.000 |
| RM1-0004-1 | PAPER PICKUP ASSY HP LJ 4200/4300 SERIES | \$ 70.000 |
| C3916-69005 | PAPER PICKUP ASSY HP LJ 5 (MEC. ARRASTRE) | \$ 20.000 |
| RG9-1082-1 | PAPER PICKUP ASSY HP LJ 5P (TRAY 1) | \$ 15.000 |
| RG5-1692-1 | PAPER PICKUP ASSY HP LJ 5P (TRAY 2) | \$ 15.000 |
| RM1-0034-1 | PAPER PICKUP DRIVE ASSY HP LJ 4200/4300 SERIES (PLATINA) | \$ 40.000 |
| 100569-1 | PERILLA CANON BJ 330 | \$ 1.000 |
| F322551140-1 | PERILLA EPSON EX 800/1000 | \$ 1.000 |
| 1002910-1 | PERILLA EPSON FX 1050/850/LQ 1050/850 | \$ 1.000 |
| 1005478-1 | PERILLA EPSON FX 1170/870/LQ 1170/870 | \$ 1.000 |
| 1039337-1 | PERILLA EPSON FX 1180/880/1180+ | \$ 1.000 |
| 1234171-1 | PERILLA EPSON FX 2190/890 | \$ 1.000 |
| 2600101-1 | PERILLA EPSON MX 100 | \$ 1.000 |
| 53562601-1 | PERILLA OKIDATA 520/521/590/591 | \$ 1.000 |
| PJBN32Z-1 | PERILLA PANASONIC KXP 1150/1121 | \$ 1.000 |
| PJBN25ZC-1 | PERILLA PANASONIC KXP 1180 | \$ 1.000 |
| PJBN29Y3-1 | PERILLA PANASONIC KXP 1695 | \$ 1.000 |
| PJBN29Z-1 | PERILLA PANASONIC KXP 3696 | \$ 1.000 |
| RG5-4128-1 | PICKUP ROLLER ASSY HP LJ 2100/2200 (TRAY 1) | \$ 30.000 |
| RF0-1008-1 | PICKUP ROLLER HP LJ 1200/1000/3300 | \$ 2.000 |
| RB2-3930-1 | PICKUP ROLLER SHAFT HP LJ 1100 SERIES/3200 | \$ 2.000 |
| 1004906-1 | PIÑON CORREA EPSON LQ 1070 (PULLEY) | \$ 2.000 |
| F336051020-1 | PIÑON CORREA EPSON LX 810 (PULLEY) | \$ 2.000 |
| 1009102-1 | PIÑON CORREA EPSON TM 300 (PULLEY) | \$ 2.000 |
| PJUJC3696-1 | PIÑON CORREA PANASONIC KXP 3696 (DER-IZQ) | \$ 2.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|--|------------|
| 1005225-1 | PIÑON ENGRANE EPSON FX 1170 (SPUR 34.5) | \$ 2.000 |
| 02276-40055-1 | PIÑON ENGRANE HP DJ 500/520/550/560 | \$ 2.000 |
| C4557-40102-1 | PIÑON ENGRANE HP DJ 710/720/810/840 | \$ 2.000 |
| C4602-40013-1 | PIÑON ENGRANE HP DJ 820/850/870/890/OFJ 1150 | \$ 2.000 |
| 1028359-1 | PIÑON INTERMITENTE EPSON FX 2180/2190/890/LQ 2070/2180/590 | \$ 1.000 |
| 1004925-1 | PIÑON INTERMITENTE EPSON LQ 1070 | \$ 1.000 |
| F334005250-1 | PIÑON RODILLO EPSON FX 1170/1050/2170 | \$ 1.000 |
| C4557-40021 | PIÑON RODILLO HP DJ 710/720/810/840 | \$ 1.000 |
| PJDG50458Z | PIÑON RODILLO PANASONIC KXP 3696 #1 | \$ 1.000 |
| PJDG50456Z | PIÑON RODILLO PANASONIC KXP 3696 #2 | \$ 1.000 |
| RS6-0566-1 | PIÑON RODILLO PRESION HP LJ 1100 | \$ 1.000 |
| F34000585P-1 | PIÑONES ENGRANE EPSON DFX 5/8/5+ | \$ 1.000 |
| 541260 | PIÑONES X6 EPSON LQ 2170 (SUELTOS) | \$ 1.000 |
| PJZUP1654M | PLATE BACK TENSION PANASONIC KXP 3696 | \$ 2.000 |
| RG5-4586-1 | PLATINA ENGRANE HP LJ 1100 | \$ 20.000 |
| RG5-4131-1 | PLATINA ENGRANE HP LJ 2100 | \$ 20.000 |
| RG5-5562-1 | PLATINA ENGRANE HP LJ 2200 | \$ 20.000 |
| RG5-2653-1 | PLATINA ENGRANE HP LJ 4000/4050 | \$ 20.000 |
| RG5-3721-1 | PLATINA ENGRANE HP LJ 4000/4050 (PEQ) | \$ 20.000 |
| RY7-5006-1 | PLATINA ENGRANE HP LJ 5L | \$ 5.000 |
| RG5-1847-1 | PLATINA ENGRANE HP LJ 5SI/8000 | \$ 25.000 |
| RG5-2778-1 | PLATINA ENGRANE HP LJ 6P | \$ 15.000 |
| 1016774-1 | PLATINA EPSON DFX 8000/5000+/8500 BUSESITO | \$ 5.000 |
| 1033459-1 | PORTACARTUCHO EPSON STY 3000 | \$ 15.000 |
| QB2-4341-1 | POWER SUPPLY CANON BJ 200E | \$ 5.000 |
| QH3-3070-1 | POWER SUPPLY CANON BJ 330 | \$ 5.000 |
| QK3-0097-1 | POWER SUPPLY CANON BJC 1000 | \$ 5.000 |
| 2009398-1 | POWER SUPPLY EPSON ACTION LASER 1500 | \$ 15.000 |
| Y475202000-1 | POWER SUPPLY EPSON DFX 5000 | \$ 60.000 |
| 2011317-1 | POWER SUPPLY EPSON DFX 5000+ | \$ 150.000 |
| 2023100-1 | POWER SUPPLY EPSON EPL 8000 | \$ 150.000 |
| 2056309-1 | POWER SUPPLY EPSON FX 1180+ | \$ 40.000 |
| 2055261-1 | POWER SUPPLY EPSON FX 880+ | \$ 40.000 |
| 2018832-1 | POWER SUPPLY EPSON FX 980/2170/2180/LQ 2080 | \$ 40.000 |
| 2005574-1 | POWER SUPPLY EPSON LQ 1070/1070+ | \$ 15.000 |
| 2018823-1 | POWER SUPPLY EPSON LQ 2170/2180 | \$ 20.000 |
| Y456202000-1 | POWER SUPPLY EPSON LQ 2550 | \$ 10.000 |
| Y463504100-1 | POWER SUPPLY EPSON LX 810 | \$ 5.000 |
| 2011012-1 | POWER SUPPLY EPSON STY 1000 | \$ 15.000 |
| 2019735-1 | POWER SUPPLY EPSON STY 1500/1520/3000 | \$ 15.000 |
| 2018212-1 | POWER SUPPLY EPSON STY 200/500 | \$ 5.000 |
| 2024562-1 | POWER SUPPLY EPSON STY 300/IIS CLR | \$ 5.000 |
| 2023062-1 | POWER SUPPLY EPSON STY 400/600/640/PHOTO | \$ 5.000 |
| C0950-01600-1 | POWER SUPPLY HP DJ 1600 | \$ 5.000 |
| 02277-60087-1 | POWER SUPPLY HP DJ 500 | \$ 5.000 |
| C4531-67810-1 | POWER SUPPLY HP DJ 820/CXI | \$ 5.000 |
| RG1-4306-1 | POWER SUPPLY HP LJ 2300 SERIES | \$ 60.000 |
| RG5-0531-1 | POWER SUPPLY HP LJ 4/4M | \$ 20.000 |
| RG5-0971-1 | POWER SUPPLY HP LJ 4+/M+/5M/5 | \$ 15.000 |
| RH3-2195-1 | POWER SUPPLY HP LJ 5000 | \$ 180.000 |
| RG1-1909-1 | POWER SUPPLY HP LJ IIP/IIIP CAJA | \$ 20.000 |
| C5300-60001-1 | POWER SUPPLY HP OFJ 1150 | \$ 20.000 |
| 55080901-1 | POWER SUPPLY OKIDATA 390T | \$ 20.000 |
| 56415101-1 | POWER SUPPLY OKIDATA 4W | \$ 15.000 |
| 56412102-1 | POWER SUPPLY OKIDATA 590/591 | \$ 25.000 |
| PJPM27ZA-1 | POWER SUPPLY PANASONIC KXP 1150 | \$ 5.000 |
| PJK03696-1 | POWER SUPPLY PANASONIC KXP 3696 | \$ 5.000 |
| RG5-3676-1 | POWER SUPPLY, BATTERY HP LJ 5SI/ 8000 | \$ 30.000 |
| RG5-0753-1 | POWER SUPPLY, DC CONTROLLER HP LJ 4L/4ML | \$ 15.000 |
| RG5-0822-1 | POWER SUPPLY, DC CONTROLLER HP LJ 4P/4MP | \$ 15.000 |
| RG5-3517-1 | POWER SUPPLY, DC CONTROLLER HP LJ 5000 | \$ 100.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|--|-----------|
| C3150-69001-1 | POWER SUPPLY, DC CONTROLLER HP LJ 5P | \$ 20.000 |
| RG5-2826-1 | POWER SUPPLY, DC CONTROLLER HP LJ 6P | \$ 20.000 |
| 07BM-7320-1 | POWER SUPPLY, DRAWER HP LJ 5M COLOR | \$ 20.000 |
| RG5-0513-1 | POWER SUPPLY, HIGH VOLTAJE HP LJ 4/4M | \$ 15.000 |
| RG5-0969-1 | POWER SUPPLY, HIGH VOLTAJE HP LJ 4+/5/5M | \$ 15.000 |
| RG5-1888-1 | POWER SUPPLY, HIGH VOLTAJE HP LJ 5SI/ 8000 | \$ 70.000 |
| RG9-0696-1 | POWER SUPPLY, HIGH VOLTAJE HP LJ IIP/IIIP | \$ 10.000 |
| F018000-1 | PRINT HEAD EPSON LQ 1170/870 | \$ 60.000 |
| 1028577-1 | PRINT HEAD EPSON TMU 200/325D/325 | \$ 40.000 |
| 1042587-1 | PRINT HEAD EPSON TMU 300/375 | \$ 45.000 |
| 1046525-1 | PRINT HEAD EPSON TMU 650/675 (+BUS) (689) | \$ 45.000 |
| 5024602-1 | PRINT HEAD OKIDATA 520/521 9PINES | \$ 75.000 |
| 1046305-1 | PULLEY CARRIAGE TRANSMISSION EPSON TMU 675 (632) | \$ 5.000 |
| 1046577-1 | RIBBON DRIVE PLATE ASSY EPSON TMU 675 (706) | \$ 5.000 |
| 1044878-1 | RIBBON MASK EPSON DFX 8000 | \$ 1.000 |
| 1045566-1 | RIBBON MASK EPSON DFX 8500 | \$ 1.000 |
| 1008710-1 | RIBBON MASK EPSON FX 1170/870 | \$ 1.000 |
| 1036497-1 | RIBBON MASK EPSON FX 1180/880 | \$ 1.000 |
| 1012621-1 | RIBBON MASK EPSON LQ 1070/1070+ | \$ 1.000 |
| B210151490-1 | RODAMIENTO PINON CORREA EPSON LX 810 | \$ 1.000 |
| 1018175-1 | RODILLITO ARRASTRE EPSON LX 300 | \$ 1.000 |
| F353002000-1 | RODILLITO ARRASTRE EPSON LX 810 | \$ 1.000 |
| RG1-1200-1 | RODILLITO ARRASTRE HP DJ 1200 | \$ 1.000 |
| C2642-60230-1 | RODILLITO ARRASTRE HP DJ 400/420 | \$ 1.000 |
| C2642-60231-1 | RODILLITO ARRASTRE HP DJ 400/420 (TAPA) | \$ 1.000 |
| C4597-40006-1 | RODILLITO ARRASTRE HP DJ 710/720/810 | \$ 1.000 |
| F338005030-1 | RODILLO EPSON FX 1050 | \$ 5.000 |
| 1008449-1 | RODILLO EPSON FX 870 | \$ 5.000 |
| 1036492-1 | RODILLO EPSON FX 880 | \$ 5.000 |
| 1005739-1 | RODILLO EPSON LQ 1070 | \$ 5.000 |
| F353252010-1 | RODILLO EPSON LX 810 | \$ 5.000 |
| 1031896-1 | RODILLO EPSON STY 1520 | \$ 5.000 |
| C2652-60239-1 | RODILLO HP DJ 400/420 (MECANISMO ARRASTRE) | \$ 5.000 |
| C2164-67812-1 | RODILLO HP DJ 600 SERIES | \$ 5.000 |
| C4557-60092-1 | RODILLO HP DJ 710/720/810/840 #1 | \$ 5.000 |
| 50114801-1 | RODILLO OKI 320T/390T | \$ 5.000 |
| 50098301-1 | RODILLO OKIDATA 520/521/590/591 | \$ 5.000 |
| 40917101-1 | ROLLER BACKUP OKIDATA 320T/321T/390T | \$ 5.000 |
| RG5-5541-1 | ROLLER DELIVERY HP LJ 2200/2300 (USED 2) | \$ 5.000 |
| RG5-5542-1 | ROLLER DELIVERY HP LJ 2200/2300 (USED 2) | \$ 5.000 |
| RM1-0371-1 | ROLLER DELIVERY HP LJ 2300 | \$ 5.000 |
| RF9-1326-1 | ROLLER DELIVERY UPPER HP LJ 4+/4/4M/5/5M | \$ 5.000 |
| RF5-1521-1 | ROLLER EXIT ASSY HP LJ 5L/6L | \$ 2.000 |
| RF5-2822-1 | ROLLER FACE-UP HP LJ 1100 | \$ 15.000 |
| RG5-5555-1 | ROLLER FEED ASSY HP LJ 2200 (TRAY 2) | \$ 35.000 |
| RG5-2651-1 | ROLLER FEED ASSY HP LJ 4000/4050 | \$ 35.000 |
| 1032230-1 | ROLLER PAPER FEED EPSON TMU 220A/B/D/PD/PB/230/P | \$ 5.000 |
| RB2-3912-1 | ROLLER PAPER FEED HP LJ 1100 | \$ 10.000 |
| RG5-5086-1 | ROLLER PAPER FEED HP LJ 4100 | \$ 5.000 |
| RM1-0012-1 | ROLLER PAPER FEED HP LJ 4200 | \$ 5.000 |
| RF5-2823-1 | ROLLER PRESSURE HP LJ 1100 | \$ 5.000 |
| RF5-1516-1 | ROLLER PRESSURE HP LJ 5L/6L | \$ 5.000 |
| RG5-2652-1 | ROLLER REGISTRATION HP LJ 4000/4050 | \$ 10.000 |
| RG5-5085-1 | ROLLER REGISTRATION HP LJ 4100 SERIES | \$ 10.000 |
| RM1-0011-1 | ROLLER REGISTRATION HP LJ 4200 | \$ 10.000 |
| RG5-1833-1 | ROLLER REGISTRATION HP LJ 5SI/ 8000 | \$ 10.000 |
| RG5-4657-1 | ROLLER TRANSFER HP LJ 1100 | \$ 5.000 |
| RG9-1483-1 | ROLLER TRANSFER HP LJ 1200/1000 | \$ 5.000 |
| RG5-4164-1 | ROLLER TRANSFER HP LJ 2100 | \$ 5.000 |
| RG5-5581-1 | ROLLER TRANSFER HP LJ 2200 | \$ 5.000 |
| RG5-4283-1 | ROLLER TRANSFER HP LJ 4000/4050 | \$ 5.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|--|-----------|
| RF5-0596-1 | ROLLER TRANSFER HP LJ 4P/4L/6P | \$ 5.000 |
| RF5-1534-1 | ROLLER TRANSFER HP LJ 5L/6L | \$ 5.000 |
| RF5-1290-1 | ROLLER TRANSFER HP LJ 5P/5MP | \$ 5.000 |
| 2009919-1 | SCANNER EPSON ACTION 1500 | \$ 10.000 |
| RG5-5591-1 | SCANNER HP LJ 2200 | \$ 80.000 |
| RG5-0449-1 | SCANNER HP LJ 4 | \$ 20.000 |
| RG5-2641-1 | SCANNER HP LJ 4000/4050 | \$ 50.000 |
| RM1-0045-1 | SCANNER HP LJ 4200 | \$ 50.000 |
| RB1-3015-1 | SCANNER HP LJ 4P/4L | \$ 15.000 |
| RG5-4811-1 | SCANNER HP LJ 5000 | \$ 15.000 |
| 07BA-6503-1 | SCANNER HP LJ 5M COLOR | \$ 10.000 |
| RG5-1780-1 | SCANNER HP LJ 5P | \$ 15.000 |
| F334005070-1 | SEGURO EJE EPSON FX 1050 | \$ 2.000 |
| 1004895-1 | SEGURO EJE EPSON LQ 1070/1070+ | \$ 2.000 |
| 1012841-1 | SEGURO EJE EPSON LX 300 | \$ 2.000 |
| F333003030-1 | SEGURO EJE EPSON LX 810 DER | \$ 2.000 |
| F333003020-1 | SEGURO EJE EPSON LX 810 IZQ | \$ 2.000 |
| 1025929-1 | SEGURO EJE EPSON STY 1520 | \$ 2.000 |
| 2026402-1 | SEGURO EJE EPSON STY 200/300/400/600/640 | \$ 2.000 |
| C6409-40021-1 | SEGURO EJE HP DJ 710/720/810/840 | \$ 2.000 |
| C4555-40043-1 | SEGURO EJE HP DJ 800 SERIE | \$ 2.000 |
| C2145-40059-1 | SEGURO EJE HP DJ 800 SERIE (TRANSPARENTE) | \$ 2.000 |
| RS5-0005-1 | SEGURO ROD.SAL PAPEL HP LJ 5L | \$ 2.000 |
| 1004913-1 | SEGURO RODILLO EPSON LQ 1070/1070+ | \$ 2.000 |
| F333003100-1 | SEGURO RODILLO EPSON LX 810 | \$ 2.000 |
| QG1-5022-1 | SENSOR DETECTOR TINTA CANON BJ 330 | \$ 2.000 |
| SEN001-2 | SENSOR ENCODER HP DJ 600 SERIES | \$ 2.000 |
| C6734-60152-1 | SENSOR HP OFJ G85 | \$ 4.000 |
| WG8-5362-1 | SENSOR OPTICAL HP LJ 4000/4050/5000 (CANT.HOJAS) | \$ 4.000 |
| F334152000-1 | SENSOR PALANCA EPSON FX 1050 | \$ 4.000 |
| F353152000-1 | SENSOR PALANCA EPSON LX 810 | \$ 4.000 |
| 2008617-1 | SENSOR PALANCA EPSON STY 300 | \$ 4.000 |
| 50803407-1 | SENSOR PALANCA OKIDATA 320/321/390 | \$ 4.000 |
| QH8-8300-1 | SENSOR PAPEL CANON BJ 330 (HOJA CONTINUA) | \$ 4.000 |
| QG3-3002-1 | SENSOR PAPEL CANON BJ 330 (HOJA SUELTA) | \$ 4.000 |
| F346155000-1 | SENSOR PAPEL EPSON DFX 5000 | \$ 4.000 |
| 1016757-1 | SENSOR PAPEL EPSON DFX 5000+/8500 (BUSESITO) | \$ 4.000 |
| 2014138-1 | SENSOR PAPEL EPSON STY 1520 | \$ 4.000 |
| 2051420-1 | SENSOR PAPEL EPSON STY 300/500/800 | \$ 4.000 |
| 2022329-1 | SENSOR PAPEL EPSON STY 400/600/640 | \$ 4.000 |
| 2006671-1 | SENSOR PAPEL EPSON TM 300 | \$ 4.000 |
| 2003375-1 | SENSOR PAPEL FRONTAL EPSON LQ 1070/1070+/570 | \$ 4.000 |
| 2032888-1 | SENSOR PAPEL FRONTAL EPSON LX 300+ | \$ 4.000 |
| C2642-80005-1 | SENSOR PAPEL HP DJ 400/420 | \$ 4.000 |
| C4557-60030 | SENSOR PAPEL HP DJ 710/720/810/840 (MTR.ROD) | \$ 4.000 |
| F344216000-1 | SENSOR PAPEL POST. EPSON LQ 2550 | \$ 4.000 |
| 2032887-1 | SENSOR PAPEL POST. EPSON LX 300+ | \$ 4.000 |
| 2011360-1 | SENSOR PAPEL POST. EPSON LX 810 | \$ 4.000 |
| RF5-3116-1 | SENSOR PAPEL TRAY 1 HP LJ 4000/4050/4100 | \$ 4.000 |
| F346151000-1 | SENSOR PLATEN GAP EPSON DFX 5000/5000+/8000/8500 | \$ 4.000 |
| 2011564-1 | SENSOR POS.INICIAL EJE EPSON DFX 5000+/8500 | \$ 4.000 |
| F331005060-1 | SENSOR POS.INICIAL EPSON FX 1050/850/LQ 2550 | \$ 4.000 |
| F333053000-1 | SENSOR POS.INICIAL EPSON LX 810/800 | \$ 4.000 |
| 2021853-1 | SENSOR POS.INICIAL EPSON STY 300/400/LQ870/1520 | \$ 4.000 |
| 2021854-1 | SENSOR POS.INICIAL EPSON STY 400/600/640/LQ1170 | \$ 4.000 |
| 2006668-1 | SENSOR POS.INICIAL EPSON TM 300 | \$ 4.000 |
| PJUP466ZA-1 | SENSOR POS.INICIAL PANASONIC KXP 3696 | \$ 4.000 |
| PJDG5922ZA-1 | SENSOR POS.INICIAL PANASONIC KXP 3696 (CIRCULAR) | \$ 4.000 |
| RG5-0475-1 | SENSOR SALIDA PAPEL HP LJ 4/4+/5/5+ POSTERIOR | \$ 4.000 |
| C4557-60062-1 | SENSOR SELECTOR PAPEL HP DJ 710/720/810/840 | \$ 4.000 |
| 2018967-1 | SENSOR TAPA EPSON FX 2170/LQ 2170/2070 | \$ 4.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|---|-----------|
| Y456305000-1 | SENSOR TAPA EPSON LQ 2550 | \$ 4.000 |
| C2145-40046-1 | SENSOR TAPA HP DJ 820/850/870/890 | \$ 4.000 |
| RG5-1984-1 | SENSOR TAPA HP LJ 5L | \$ 4.000 |
| RG5-3453-1 | SENSOR TAPA HP LJ 6L | \$ 4.000 |
| PJUST3696-1 | SENSOR TAPA PANASONIC KXP 3696 | \$ 4.000 |
| X620900621-1 | SENSOR TAPA POS. EPSON DFX 5000/5000+/8000 | \$ 4.000 |
| 2000606-1 | SENSOR TAPA SUP. EPSON DFX 8000/5000/5000+ | \$ 4.000 |
| 2028687-1 | SENSOR TAPA SUP. EPSON DFX 8500 | \$ 4.000 |
| C4555-60086-1 | SEPARADOR RODILLITO ARRASTRE HP DJ 600/800 SERIES | \$ 2.000 |
| 12G6779-1 | SEPARATION ARM PAD LEXMARK E210 | \$ 3.000 |
| RF0-1014-1 | SEPARATION PAD HP LJ 1200 | \$ 3.000 |
| RF5-0343-1 | SEPARATION PAD HP LJ 4/4+/5/5P/6P/5M | \$ 3.000 |
| QG2-0246-1 | SERVICE STATION CANON BJ 200/240/250 | \$ 3.000 |
| QA2-0629-1 | SERVICE STATION CANON BJ 330 | \$ 3.000 |
| QB1-0880-1 | SERVICE STATION CANON BJ 600 | \$ 3.000 |
| 1018513-1 | SERVICE STATION EPSON STY 1000 | \$ 5.000 |
| 1036753-1 | SERVICE STATION EPSON STY 3000 | \$ 15.000 |
| 1021000-1 | SERVICE STATION EPSON STY 400 | \$ 5.000 |
| 1040515-1 | SERVICE STATION EPSON STY 640 | \$ 5.000 |
| 1017030-1 | SERVICE STATION EPSON STY CLR 200/300 | \$ 5.000 |
| C2642-60260-1 | SERVICE STATION HP DJ 400/420 | \$ 5.000 |
| C4462-00656-1 | SERVICE STATION HP DJ 656 | \$ 5.000 |
| C2145-67850-1 | SERVICE STATION HP DJ 820/850/855/870/890 | \$ 5.000 |
| C5500-01150 | SERVICE STATION HP OFJ 1150 | \$ 5.000 |
| 1046303-1 | SHAFT CARRIAGE GUIDE EPSON TMU 675 (631) | \$ 5.000 |
| 1046573-1 | SLIP T.O.F DETECT ASSY EPSON TMU 675 (703) | \$ 5.000 |
| RH7-5270-1 | SOLENOIDE HP LJ 2200 | \$ 5.000 |
| RB1-8671-1 | SUPPORT, TOP COVER, LEFT HP LJ 4000/4050/4100 | \$ 15.000 |
| 12214-1 | SWITCH ENCENDIDO EPSON TM 300 | \$ 10.000 |
| 2006186-1 | SWITCH ENCENDIDO EPSON TMU 300 | \$ 10.000 |
| 2030853-1 | SWITCH PANEL CIRCUIT BOARD ASSY EPSON TMU 675 (204) | \$ 15.000 |
| F338552000-1 | TAPA ACRILICA EPSON FX 1050 | \$ 15.000 |
| 1009559-1 | TAPA ACRILICA EPSON FX 870 | \$ 15.000 |
| 1033606-1 | TAPA ACRILICA EPSON STY 3000 (BANDEJA) | \$ 15.000 |
| 50441002-1 | TAPA ACRILICA OKIDATA 320/321/390 | \$ 15.000 |
| PJKK158Z-1 | TAPA ACRILICA PANASONIC KXP 3696 | \$ 15.000 |
| 1025039-1 | TAPA BANDEJA FRONTAL EPSON FX/LQ 2170/2070/2180 | \$ 15.000 |
| QH2-3159-1 | TAPA FRONTAL CANON BJC 210 | \$ 5.000 |
| 1037993-1 | TAPA FRONTAL EPSON DFX 8500 | \$ 15.000 |
| 1037983-1 | TAPA FRONTAL EPSON DFX 8500 (LOGO) | \$ 15.000 |
| 1266429-1 | TAPA FRONTAL EPSON FX 2190 | \$ 15.000 |
| 1036539-1 | TAPA FRONTAL EPSON FX 880 | \$ 15.000 |
| 1006081-1 | TAPA FRONTAL EPSON LQ 1070 | \$ 15.000 |
| RG0-1091-1 | TAPA FRONTAL HP LJ 1000 (LOGO) | \$ 15.000 |
| R37-5000-1 | TAPA FRONTAL HP LJ 1100A (SCANNER) | \$ 15.000 |
| RA0-1177-1 | TAPA FRONTAL HP LJ 1200/1000 | \$ 15.000 |
| RG5-5298-1 | TAPA FRONTAL HP LJ 4100 SERIES | \$ 15.000 |
| RF0-1073-1 | TAPA LATERAL DERECHA HP LJ 1000/1200 | \$ 15.000 |
| RG5-4123-1 | TAPA LATERAL DERECHA HP LJ 2100 (DIMM COVER ASSY) | \$ 15.000 |
| RG5-5545-1 | TAPA LATERAL DERECHA HP LJ 2200 (DIMM COVER ASSY) | \$ 15.000 |
| RM1-0329-1 | TAPA LATERAL DERECHA HP LJ 2300 | \$ 15.000 |
| RB1-7881-1 | TAPA LATERAL HP LJ 5 (DERECHA-IZQUIERDA 1 PAR) | \$ 10.000 |
| RA0-1403-1 | TAPA LATERAL IZQUIERDA HP LJ 1000 | \$ 15.000 |
| RG5-5549-1 | TAPA LATERAL IZQUIERDA HP LJ 2200 | \$ 15.000 |
| 1042680-1 | TAPA POSTERIOR EPSON DFX 8500 | \$ 15.000 |
| RG5-5546-1 | TAPA POSTERIOR HP LJ 2200 | \$ 5.000 |
| RF5-1645-1 | TAPA POSTERIOR HP LJ 5 | \$ 5.000 |
| 1013820-1 | TAPA SUPERIOR EPSON ACTION 1500 | \$ 5.000 |
| 1001044-1 | TAPA SUPERIOR EPSON DFX 8000 | \$ 10.000 |
| 1031902-1 | TAPA SUPERIOR EPSON STY 1520 | \$ 10.000 |
| RA0-1401-1 | TAPA SUPERIOR HP LJ 1000 | \$ 10.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|---|-----------|
| RG0-1017-1 | TAPA SUPERIOR HP LJ 1200 | \$ 10.000 |
| RG5-4122-1 | TAPA SUPERIOR HP LJ 2100 SERIES | \$ 15.000 |
| RG5-2663-1 | TAPA SUPERIOR HP LJ 4000/4050/4100 SERIES | \$ 15.000 |
| RG5-1870-1 | TAPA SUPERIOR HP LJ 5SI/8000 | \$ 15.000 |
| RB2-2856-1 | TAPA TONER SUPERIOR HP LJ 2100/2200 SERIES | \$ 15.000 |
| RB1-3474-1 | TAPA TONER SUPERIOR HP LJ 4+ | \$ 10.000 |
| RG5-2782-1 | TAPA TONER SUPERIOR HP LJ 6P | \$ 10.000 |
| 2048039-1 | TARJETA PARALELA EPSON TMU 200PB/PD/220PA/PB/230P/300PD | \$ 60.000 |
| 2023807-1 | TARJETA SWITCH EPSON DFX 8500 | \$ 20.000 |
| C2642-60220-1 | TENSION CORREA HP DJ 400 SERIES | \$ 0 |
| C2114-40052-1 | TENSION CORREA HP DJ 500 SERIES | \$ 2.000 |
| C2162-40016-1 | TENSION CORREA HP DJ 600 SERIES | \$ 2.000 |
| C4557-60109-1 | TENSION CORREA HP DJ 710/720/810/930/950/920 | \$ 2.000 |
| C4555-60067-1 | TENSION CORREA HP DJ 820/850/870/890 IDLER | \$ 2.000 |
| C4555-60068-1 | TENSION CORREA HP DJ 820/850/870/890/OFJ 1150 | \$ 2.000 |
| RM1-0049-1 | TOP COVER ASSY HP LJ 4200/4300 SERIES | \$ 25.000 |
| QA2-1008-000 | TRACTOR DERECHO CANON BJ 330 | \$ 5.000 |
| 1010273-1 | TRACTOR DERECHO EPSON FX 1170/1050/870/850/LQ1170 | \$ 10.000 |
| 1025294-1 | TRACTOR DERECHO EPSON FX/LQ 2170/2070/STY1500 | \$ 10.000 |
| 1018217-1 | TRACTOR DERECHO EPSON LX 300 | \$ 10.000 |
| F353253050-1 | TRACTOR DERECHO EPSON LX 810/LQ 1070 | \$ 10.000 |
| 53350302-1 | TRACTOR DERECHO OKIDATA 320/390 | \$ 10.000 |
| 53350322 | TRACTOR DERECHO OKIDATA 520/521/59/591 | \$ 10.000 |
| PJDT138Z-1 | TRACTOR DERECHO PANASONIC KXP 1150 | \$ 10.000 |
| PJDT63ZB-1 | TRACTOR DERECHO PANASONIC KXP 1595 | \$ 10.000 |
| 1019883-1 | TRACTOR FRON.DERECHO EPSON DFX 5000/8000 | \$ 10.000 |
| 1043948-1 | TRACTOR FRON.DERECHO EPSON DFX 5000+/8500 | \$ 10.000 |
| QA2-1007-000 | TRACTOR IZQUIERDO CANON BJ 330 | \$ 10.000 |
| 1010272-1 | TRACTOR IZQUIERDO EPSON FX 1170/1050/870/850/LQ1170 | \$ 10.000 |
| 1025293-1 | TRACTOR IZQUIERDO EPSON FX/LQ 2170/2070/STY1500 | \$ 10.000 |
| 1016339-1 | TRACTOR IZQUIERDO EPSON LQ 1070/+ /LX 810 | \$ 10.000 |
| 1018218-1 | TRACTOR IZQUIERDO EPSON LX 300 | \$ 10.000 |
| F353253040-1 | TRACTOR IZQUIERDO EPSON LX 810/LQ 1070 | \$ 10.000 |
| 53350202 | TRACTOR IZQUIERDO OKIDATA 320 | \$ 10.000 |
| 53350202-1 | TRACTOR IZQUIERDO OKIDATA 320/390 | \$ 10.000 |
| 54350302 | TRACTOR IZQUIERDO OKIDATA 321 | \$ 10.000 |
| 53350323 | TRACTOR IZQUIERDO OKIDATA 520/521/590/591 | \$ 10.000 |
| PJUT137Z-1 | TRACTOR IZQUIERDO PANASONIC KXP 1150 | \$ 10.000 |
| 1019886-1 | TRACTOR POST.DERECHO EPSON DFX 5000/8000 | \$ 10.000 |
| 1043950-1 | TRACTOR POST.DERECHO EPSON DFX 5000+/8500 | \$ 10.000 |
| 1043947-1 | TRACTOR POST.IZQUIERDO EPSON DFX 5000+/8500 | \$ 10.000 |
| 56412402-1 | TRANSFORMADOR OKIDATA 520/521 | \$ 10.000 |
| C3456-1 | TRANSISTOR FUENTE REF.C3456 EPSON DFX 8000 | \$ 15.000 |
| K1606-1 | TRANSISTOR FUENTE REF.K1606 EPSON FX 1170 | \$ 14.000 |
| D2131-1 | TRANSISTOR REF.D2131 EPSON FX 1180 | \$ 5.000 |
| RG5-5576-1 | TRAY 1 ASSY HP LJ 2200 SERIES | \$ 35.000 |
| RB1-7885-1 | TRAY 1 EXTENDER HP LJ 5 | \$ 15.000 |
| RM1-0005-1 | TRAY 1 HP LJ 4200/4300 SERIES (DROP DOWN) | \$ 30.000 |
| RM1-0353-1 | TRAY 1 MULTI-PORPUSE HP LJ 2300 SERIES | \$ 25.000 |
| RB2-2037-1 | TRAY 2 CASSETTE HP LJ 5000 (250 SHEET) | \$ 40.000 |
| RG0-1006-1 | TRAY ASSY, PAPER LIFT HP LJ 1200/1000 | \$ 15.000 |
| C7065B-1 | TRAY CASSETTE HP LJ 2200 (500 SHEET) | \$ 20.000 |
| 1408792-1 | UNIDAD TRACTOR EPSON FX 2190 | \$ 25.000 |
| 1011006-1 | UNIDAD TRACTOR EPSON FX 870 | \$ 25.000 |
| 1013479-1 | UNIDAD TRACTOR EPSON LQ 1070/1070+ | \$ 25.000 |
| 1033927-1 | UNIDAD TRACTOR EPSON STY 3000 | \$ 25.000 |
| 5310521-1 | UNIDAD TRACTOR OKIDATA ML 521 | \$ 25.000 |
| 2000155-1 | VENTILADOR EPSON DFX 8000/8500 | \$ 2.000 |
| 2026599-1 | VENTILADOR EPSON DFX 8500 (MTR. CARRO) | \$ 2.000 |
| 2003084-1 | VENTILADOR EPSON LQ 1170 | \$ 2.000 |
| Y654804000-1 | VENTILADOR EPSON MX 100 | \$ 2.000 |



PARTES USADAS - EXCELENTES CONDICIONES DE FUNCIONAMIENTO Y GARANTIA

| Código | Descripcion | PRECIO |
|---------------|--|----------|
| 3160-0831-1 | VENTILADOR HP DJ 1200/1600 | \$ 2.000 |
| C2145-60036-1 | VENTILADOR HP DJ 820/850/855 | \$ 2.000 |
| RH7-1383-1 | VENTILADOR HP LJ 2100 SERIES | \$ 2.000 |
| RH7-1463-1 | VENTILADOR HP LJ 2200 SERIES | \$ 2.000 |
| RH7-1591-1 | VENTILADOR HP LJ 2300 | \$ 2.000 |
| RH7-1144-1 | VENTILADOR HP LJ 4 | \$ 2.000 |
| RH7-1335-1 | VENTILADOR HP LJ 4000/4050 | \$ 2.000 |
| RH7-1442-1 | VENTILADOR HP LJ 4100 | \$ 2.000 |
| RH7-1158-1 | VENTILADOR HP LJ 4L | \$ 2.000 |
| RH7-1183-1 | VENTILADOR HP LJ 4P | \$ 2.000 |
| RH7-1178-1 | VENTILADOR HP LJ 5 | \$ 2.000 |
| RH7-1354-1 | VENTILADOR HP LJ 5000 | \$ 2.000 |
| RG5-1801-1 | VENTILADOR HP LJ 5P | \$ 2.000 |
| RH7-1266-1 | VENTILADOR HP LJ 5SI | \$ 2.000 |
| 07BM-1081-1 | VENTILADOR HP LJ COLOR 5/5M (FM4) | \$ 2.000 |
| 07BA-1340-1 | VENTILADOR HP LJ COLOR 5/5M (FM9) | \$ 2.000 |
| RH7-1056-1 | VENTILADOR HP LJ II/III (LOWER) | \$ 2.000 |
| RH7-1121-1 | VENTILADOR HP LJ IIP/IIIP | \$ 2.000 |
| C5300-00022-1 | VENTILADOR HP OFJ 1150 | \$ 2.000 |
| RH7-1573-1 | VENTILADOR LEFT HP LJ 4200/4300 SERIES | \$ 2.000 |
| VEN001-1 | VENTILADOR VARIOS | \$ 2.000 |
| C2642-80400-1 | VISOR PANEL CONTROL HP DJ 400 | \$ 2.000 |
| C2642-80420-1 | VISOR PANEL CONTROL HP DJ 420 | \$ 2.000 |